





report date: 2024-03-28

### General information

Make	VAUXHALL
Model	AGILA SE
Colour	Silver
Year of manufacture	2012
Top speed	106 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	92 BHP	
Max. torque	118 Nm at 4.800 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	40.9 mpg	
Consumption extra urban	56.5 mpg	
Consumption combined	49.6 mpg	
CO2 emission	131 g/km	
CO2 label	E	



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2022-02-16

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-15
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #12		2024-02-16 12:03
<b>MOT</b> test	number	685560888611
Result		✓ Passed
Next expiry date 2025-02-		2025-02-15
Advice Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))		
Advice	Oil leak, but not excessive oil filter (8.4.1 (a) (i))	

2023-02-14 14:45
502517906995
✓ Passed
2021-12-09 11:03
270460134678
<b>✓</b> Passed

MOT #9	2020-12-16 11:41
MOT test number	195461620707
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



Result

YS12XDK report date: 2024-03-28

Passed

MOT #8 2020-12-15 15:04

MOT test number 148840068487

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7 2020-05-21 10:29

**MOT test number** 793680191978

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin Close to limit (1.1.13 (a) (ii))

**MOT #6** 2019-05-20 13:13

**MOT test number** 977701477768

**Result** ✓ Passed

**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2018-05-21 11:26

**MOT test number** 312201816327

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2017-05-26 08:24

MOT test number 255721828046

**Result** 
✓ Passed

**Advice** Offside Rear tyre slightly perished

Advice Front tyres slightly perished

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Offside Rear tyre slightly perished

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Front tyres slightly perished

 MOT #2
 2016-05-25 09:55

 MOT test number
 737863362667

 Result
 ✓ Passed

 MOT #1
 2015-06-02 14:41

 MOT test number
 365573655102

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



YS12XDK

report date: 2024-03-28

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category


**Type** 

**Date** 

Damage 2

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	7
Current registration	AIR AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-19
Last registration	2024-02-16
Complete history	See info



Registration #1	2012-07-19	11 mi
Registration #2	2015-06-02	10.606 mi
Registration #3	2016-05-25	14.306 mi
Registration #4	2017-05-26	16.727 mi
Registration #5	2017-05-26	16.727 mi
Registration #6	2018-05-21	19.702 mi
Registration #7	2019-05-20	22.211 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.177 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

## Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1511813

CarCheck.co.uk page 12/12