





report date: 2024-03-29

General information

Make	VOLVO
Model	S90 D4 R-DESIGN PRO
Colour	Blue
Year of manufacture	2017
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
	200 2
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



BD17ETY

report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



BD17ETY

report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-04-12
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	1
Total items failed	6

MOT #9	2024-03-27 14:32
MOT test number	419664311647
Result	✓ Passed
Next expiry date	2025-04-12

MOT #8	2023-03-30 14:03
MOT test number	989124096819
Result	✓ Passed

MOT #7	2022-03-21 15:45
MOT test number	156786509539
Result	✓ Passed

MOT #6	2022-03-16 16:03
MOT test number	172588496808

Result

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

CarCheck.co.uk page 3/11



BD17ETY

report date: 2024-03-29

MOT #5 2021-04-13 08:16

MOT test number 118195454901

MOT #4 2021-04-09 14:57

MOT test number 745507037095

Result X Failed

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #3 2020-06-20 10:04

MOT test number 892674368553

Result ✓ Passed

MOT #2 2020-06-17 13:56

MOT test number 244780239164

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1 2020-05-11 07:25

MOT test number 191254330387

Result ✓ Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when mistery		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		

	More info >	
Plate changes See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-05-19
Last registration	2024-03-27
Complete history	See info



Registration #1	2017-05-19	6 mi
Registration #2	2020-06-17	30.940 mi
Registration #3	2020-06-20	30.940 mi
Registration #4		11.777 es
Registration #5	2021-04-09	31.521 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea 11.777 ea
		11.77 m
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page	e 11/11

Number of axles 2

Engine number 2084394