



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO ACTIVE
Colour	Grey
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-11-06
Pictures	36
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-15
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	35
Total items failed	11

MOT #17	2022-11-15 12:10
MOT test number	657381811567
Result	✓ Passed
Next expiry date	2023-11-15
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-11-16 14:07
MOT test number	601373745477
Result	✓ Passed

MOT #15	2021-07-07 16:07
MOT test number	272408031010
Result	✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front All direction indicators slightly discoloured (4.4.3 (a))
Advice	Rear exhaust system outer skin coming adrift
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Gearbox oil leak

**MOT #14** 2021-07-07 12:03**MOT test number** 647791542784**Result** ✗ Failed**Advice** Rear exhaust system outer skin coming adrift**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (I))**Fail** Nearside Front Position lamp not working side light (4.2.1 (a) (ii))**Advice** Offside Front All direction indicators slightly discoloured (4.4.3 (a))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Gearbox oil leak**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Position lamp not working side light (4.2.1 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-06-06 09:19**MOT test number** 327310264998**Result** ✓ Passed**MOT #12** 2020-06-06 09:19**MOT test number** 873734946421**Result** ✗ Failed**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2020-03-14 07:54**MOT test number** 781255898689**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear exhaust silencer corroded and in poor condition.**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2019-01-09 12:48**MOT test number** 867942673503**Result** ✓ Passed**Advice** Rear exhaust rear box corroded**Advice** Rear Coil spring corroded both springs corroded (5.3.1 (b) (i))**Advice** Front shocks on from noisy under operation**Advice** Nearside Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Shock absorbers has slight external damage to the casing both rear shocks corroded (5.3.2 (b))**MOT #9** 2018-01-11 10:44**MOT test number** 962820179226**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Rear back box starting to corrode**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #8** 2017-01-06 14:32**MOT test number** 364342599993**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases rear back box (7.1.2)**MOT #7** 2016-01-08 16:43**MOT test number** 321507251172**Result** ✓ Passed**Advice** Rear both tyres perished and cracked, recommend replacing**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-01-08 15:03**MOT test number** 597292093624**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear both tyres perished and cracked, recommend replacing**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-01-14 11:38**MOT test number** 815054615016**Result** ✓ Passed**MOT #4** 2014-10-11 09:30**MOT test number** 349744084212**Result** ✓ Passed

**MOT #3** 2013-09-14 10:03**MOT test number** 478637753222**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #2** 2012-10-05 13:01**MOT test number** 308139072421**Result** ✓ Passed**Notice** Rear exhaust slightly deteriorated**MOT #1** 2011-09-06 09:51**MOT test number** 649929041237**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-25
Last registration	2022-11-15
Complete history	See info



Registration #1	2008-09-25	16 mi
Registration #2	2011-09-06	24.747 mi
Registration #3	2012-10-05	32.148 mi
Registration #4	2013-09-14	34.475 mi
Registration #5	2014-10-11	36.718 mi
Registration #6	2015-01-14	36.717 mi
Registration #7	2016-01-08	43.688 mi
Registration #8	2016-01-08	43.688 mi
Registration #9	2017-01-06	51.126 mi
Registration #10	2018-01-11	60.146 mi
Registration #11	2019-01-06	68.166 mi
Registration #12	2019-01-06	68.166 mi
Registration #13	2019-01-06	68.166 mi
Registration #14	2019-01-06	68.166 mi
Registration #15	2019-01-06	68.166 mi
Registration #16	2019-01-06	68.166 mi
Registration #17	2019-01-06	68.166 mi
Registration #18	2019-01-06	68.166 mi
Registration #19	2019-01-06	68.166 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4708035