



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI SE 174PS DPF
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.0 mpg
CO2 emission	286 g/km
CO2 label	M






Internet history

Entry 2

Date	2021-07-09
Pictures	44
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-06-17
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	48
Total items failed	1

MOT #19	2023-11-15 10:14
MOT test number	430712869574
Result	✓ Passed
Next expiry date	2024-12-08
Advice	Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))

MOT #18	2022-12-07 14:34
MOT test number	193763664513
Result	✓ Passed
Advice	Nearside Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))
Advice	Offside Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

**MOT #17**

2022-12-07 10:02

MOT test number

911695076167

Result**✗ Failed**

Advice Nearside Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

Advice Offside Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))

DANGEROUS Nearside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

MOT #16

2021-12-09 09:21

MOT test number

765763970806

Result**✓ Passed**

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15

2021-01-12 15:25

MOT test number

507866991683

Result**✓ Passed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #14

2021-01-11 16:51

MOT test number

638938931268

Result**✗ Failed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #13**

2020-01-03 14:39

MOT test number

627556276349

Result

✓ Passed

- Advice** Oil leak
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #12

2020-01-02 10:52

MOT test number

384166777917

Result

✗ Failed

- DANGEROUS** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Oil leak
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #11**

2019-12-18 09:47

MOT test number

412407293213

Result**✗ Failed**

- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit 0.6 plate limit (8.2.2.2 (a))

MOT #10

2018-12-21 12:30

MOT test number

139320321790

Result**✓ Passed****MOT #9**

2018-03-08 10:59

MOT test number

887512562608

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Wheel bearing noise detected on road test
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Front suspension has slight movement at a suspension ball joint (2.5.A.1c)

**MOT #8** 2017-02-08 12:27**MOT test number** 399394152735**Result** ✓ Passed**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2017-02-08 12:27**MOT test number** 894064604041**Result** ✗ Failed**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #6** 2016-03-07 14:58**MOT test number** 480251457750**Result** ✓ Passed**MOT #5** 2014-05-09 13:21**MOT test number** 457409324189**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2013-05-09 10:52**MOT test number** 966269423173**Result** ✓ Passed**Notice** H/brake warning light intermitantly sticking on. Attention required**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2012-05-02 11:47**MOT test number** 655603922163**Result** ✓ Passed



MOT #2	2011-05-06 14:30
MOT test number	105576421164
Result	✓ Passed
<div><div>Advice</div>Offside Front Lower Radius arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)</div> <div><div>Advice</div>Nearside Front Lower Radius arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)</div>	
MOT #1	2010-03-22 11:20
MOT test number	552481580033
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
8 December 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	8 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	DE07HLD
Plate since	2019-06-29
Current registration	DE07HLD
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-05
Last registration	2023-11-15
Complete history	See info



Registration #1	2007-04-05	27 mi
Registration #2	2010-03-22	17.166 mi
Registration #3	2011-05-06	22.194 mi
Registration #4	2012-05-02	28.727 mi
Registration #5	2013-05-09	32.867 mi
Registration #6	2014-05-09	45.445 mi
Registration #7	2016-03-07	69.179 mi
Registration #8	2017-02-08	76.529 mi
Registration #9	2017-02-08	76.529 mi
Registration #10	2018-03-08	83.449 mi
Registration #11	2018-12-21	88.879 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi
Registration #21	2019-05-20	95.377 mi
Registration #22	2019-05-20	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1723 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2229 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BPE 003437