



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Blue
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





## Internet history

### Entry 3


Date	2023-01-12
Pictures	40
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

### Entry 2



Date	2023-01-12
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

### Entry 1

Date	2022-01-18
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-20
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	18
Total items failed	8

MOT #12	2024-01-18 11:29
MOT test number	151653009446
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2023-01-04 12:00
MOT test number	581899577300
Result	✓ Passed

MOT #10	2022-01-21 16:42
MOT test number	146417504666
Result	✓ Passed

MOT #9	2022-01-19 16:37
MOT test number	365773566039
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #8**

2021-02-25 15:41

**MOT test number**

707765370965

**Result**

✓ Passed

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #7**

2021-02-25 10:35

**MOT test number**

772919118766

**Result**

✗ Failed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #6**

2020-03-02 10:49

**MOT test number**

752395959770

**Result**

✓ Passed

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Exhaust tailpipe corroded and broken at support bracket but system still adequately supported

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #5** 2019-03-04 15:29**MOT test number** 180515394712**Result** ✓ Passed**MOT #4** 2019-03-04 09:29**MOT test number** 468457983215**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both also perished (5.2.3 (e))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both also perished (5.2.3 (e))**MOT #3** 2018-03-06 13:39**MOT test number** 361136556442**Result** ✓ Passed**MOT #2** 2018-03-06 10:15**MOT test number** 313108763802**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #1** 2017-03-30 08:56**MOT test number** 835449937073**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
20 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	20 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2015-05-29
Current registration	
Plate since	2015-05-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2015-03-10
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2015-03-10	18 mi
Registration #2	2017-03-30	26.603 mi
Registration #3	2018-03-06	32.505 mi
Registration #4	2018-03-06	32.505 mi
Registration #5	2019-03-04	41.934 mi
Registration #6	2019-03-04	41.934 mi
Registration #7	2020-03-02	51.640 mi
Registration #8	2021-02-25	56.010 mi
Registration #9	2022-03-02	56.010 mi
Registration #10	2022-03-02	56.010 mi
Registration #11	2022-03-02	56.010 mi
Registration #12	2022-03-02	56.010 mi
Registration #13	2022-03-02	56.010 mi
Registration #14	2022-03-02	56.010 mi
Registration #15	2022-03-02	56.010 mi
Registration #16	2022-03-02	56.010 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961