




report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | SCIROCCO GT |
| Colour | Red |
| Year of manufacture | 2008 |
| Top speed | 145 mph |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 200 BHP |
| Max. torque | 280 Nm at 1.700 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 37.2 mpg |
| CO2 emission | 179 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-06 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-09 |
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 26 |
| Total items failed | 12 |

| | |
|------------------|--|
| MOT #18 | 2023-06-10 09:48 |
| MOT test number | 811783513386 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-09 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Minor | Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge + perishing (5.2.3 (e)) |

**MOT #17**

2023-06-10 09:48

MOT test number

496940943435

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge + perishing (5.2.3 (e))
- Pass with rectification** Front Headlamp aim too low x2 osf / nsf (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16

2022-04-28 16:18

MOT test number

508214754187

Result**✓ Passed**

- Advice** Rear Inner Tyre worn close to legal limit/worn on edge x2 osr / nsr (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inner Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))

**MOT #15** 2022-04-27 16:37**MOT test number** 324293899111**Result** ✗ Failed

- Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Inner Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))
- Advice** Rear Inner Tyre worn close to legal limit/worn on edge x2 osr / nsr (5.2.3 (e))

MOT #14 2020-11-25 14:41**MOT test number** 337875082520**Result** ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2020-01-25 12:13**MOT test number** 657256996339**Result** ✓ Passed**MOT #12** 2019-02-01 08:51**MOT test number** 770633369954**Result** ✓ Passed

**MOT #11** 2019-01-22 12:32**MOT test number** 237442660417**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front and rear pads wearing thin**MOT #10** 2018-01-30 15:40**MOT test number** 247427520355**Result** ✓ Passed**MOT #9** 2017-01-10 14:40**MOT test number** 308841148672**Result** ✓ Passed**MOT #8** 2017-01-09 15:21**MOT test number** 200431465845**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #7** 2016-01-06 12:28**MOT test number** 680293967594**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-01-07 10:33**MOT test number** 179207405056**Result** ✓ Passed**MOT #5** 2015-01-07 10:33**MOT test number** 787357405051**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2014-01-10 12:32**MOT test number** 146400214033**Result** ✓ Passed**MOT #3** 2012-11-05 10:30**MOT test number** 657230512395**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Rear tyre treads slight distortion**MOT #2** 2011-11-12 09:50**MOT test number** 245026711336**Result** ✓ Passed**MOT #1** 2011-11-12 09:50**MOT test number** 555066911310**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
9 June 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 9 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  ML58WFX |
| Plate since | 2019-06-29 |
| Current registration |  ML58WFX |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2008-11-13 |
| Last registration | 2023-06-10 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2008-11-13 | 19 mi |
| Registration #2 | 2011-11-12 | 14.990 mi |
| Registration #3 | 2012-11-05 | 19.397 mi |
| Registration #4 | 2014-01-10 | 23.817 mi |
| Registration #5 | 2015-01-07 | 44.861 mi |
| Registration #6 | 2016-01-06 | 56.989 mi |
| Registration #7 | 2017-01-09 | 70.037 mi |
| Registration #8 | 2017-01-10 | 70.037 mi |
| Registration #9 | 2018-01-30 | 81.613 mi |
| Registration #10 | 2019-01-01 | 91.217 mi |
| Registration #11 | 2019-01-01 | 91.217 mi |
| Registration #12 | 2019-01-01 | 91.217 mi |
| Registration #13 | 2019-01-01 | 91.217 mi |
| Registration #14 | 2019-01-01 | 91.217 mi |
| Registration #15 | 2019-01-01 | 91.217 mi |
| Registration #16 | 2019-01-01 | 91.217 mi |
| Registration #17 | 2019-01-01 | 91.217 mi |
| Registration #18 | 2019-01-01 | 91.217 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1404 mm |
| Length | 4256 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1318 kg |
| Max. allowed weight | 1740 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | CAW 019753 |