



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE S VVT 111 SCENIC
Colour	Gold
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-23
Pictures	37
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #15</b>	2023-07-01 13:03
<b>MOT test number</b>	387822716671
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-06-30
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

<b>MOT #14</b>	2023-06-27 09:10
<b>MOT test number</b>	704050273592
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b>	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Fail</b>	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
<b>Fail</b>	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Fail</b>	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

<b>MOT #13</b>	2022-06-18 09:18
<b>MOT test number</b>	498653968103
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #12</b>	2021-06-17 13:36
<b>MOT test number</b>	473007050082
<b>Result</b>	✓ Passed

**MOT #11** 2020-06-22 09:46**MOT test number** 225046390157**Result** ✓ Passed**MOT #10** 2020-06-20 11:20**MOT test number** 694053795695**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2019-06-11 08:10**MOT test number** 516873333166**Result** ✓ Passed**Advice** O/s steering tie rod has slight play**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge edge wearing (5.2.3 (e))**MOT #8** 2018-06-15 15:38**MOT test number** 455581357966**Result** ✓ Passed**Advice** Both front tyres have slight wear on edges**MOT #7** 2018-06-15 07:58**MOT test number** 680942161375**Result** ✗ Failed**Advice** Both front tyres have slight wear on edges**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Rear Tyre has ply or cords exposed sidewall cracked (5.2.3 (d) (ii))

**MOT #6** 2017-06-21 13:36**MOT test number** 672014201108**Result** ✓ Passed**MOT #5** 2016-06-22 14:57**MOT test number** 650458214391**Result** ✓ Passed**MOT #4** 2014-07-24 17:24**MOT test number** 706165604205**Result** ✓ Passed**MOT #3** 2013-09-09 12:19**MOT test number** 346232153216**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-08-24 15:56**MOT test number** 977127532227**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Both front tyres perished and splitting**Notice** Nail in offside rear tyre**MOT #1** 2011-08-17 11:31**MOT test number** 797569521227**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	KY58SXU
Plate since	2019-03-29
Current registration	KY58SXU
Plate since	2019-03-29

More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-11
Last registration	2023-07-01
Complete history	<a href="#">See info</a>



Registration #1	2008-09-11	15 mi
Registration #2	2011-08-17	14.373 mi
Registration #3	2012-08-24	21.229 mi
Registration #4	2013-09-09	25.728 mi
Registration #5	2014-07-24	29.001 mi
Registration #6	2016-06-22	42.703 mi
Registration #7	2017-06-21	48.019 mi
Registration #8	2018-06-15	56.723 mi
Registration #9	2018-06-15	56.723 mi
Registration #10	2019-06-21	56.723 mi
Registration #11	2019-06-21	56.723 mi
Registration #12	2019-06-21	56.723 mi
Registration #13	2019-06-21	56.723 mi
Registration #14	2019-06-21	56.723 mi
Registration #15	2019-06-21	56.723 mi
Registration #16	2019-06-21	56.723 mi
Registration #17	2019-06-21	56.723 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

D053480