



report date: 2024-03-29

General information

Make	FIAT
Model	500 C TWINAIR PLUS
Colour	Blue
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 3

Date 2022-12-30

Pictures 8

Listing price [View report](#)



source: autotrader.co.uk

Entry 2

Date 2022-12-16

Pictures 8

Listing price [View report](#)





source: autotrader.co.uk

Entry 1

Date 2021-10-21

Pictures 20

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	28
Total items failed	5

MOT #12	2024-01-19 09:57
MOT test number	793349736863
Result	✓ Passed
Next expiry date	2025-01-18

MOT #11	2023-01-11 11:48
MOT test number	154070437461
Result	✓ Passed

MOT #10	2022-02-19 14:07
MOT test number	300534030361
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2022-02-19 09:34

MOT test number

298316491038

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure bulge in outer sidewall (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8**

2021-02-11 16:50

MOT test number

791508048198

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Coolant leak**MOT #7**

2020-02-20 10:14

MOT test number

520832600486

Result**✓ Passed****Advice** Front exhaust flexy joint deteriorated**Advice** Nearside Rear Nail in tyre

**MOT #6** 2019-03-28 14:46**MOT test number** 203464161845**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #5 2019-03-27 12:14**MOT test number** 794573576830**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #4 2018-03-27 10:35**MOT test number** 461437913046**Result** ✓ Passed

- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)



MOT #3	2017-03-25 11:37
MOT test number	198513975446
Result	✓ Passed

MOT #2	2016-03-22 11:21
MOT test number	448018621471
Result	✓ Passed
Advice	Oil leak from gearbox area
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2015-02-28 11:21
MOT test number	395469955001
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Oil leak
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-27
Last registration	2024-01-19
Complete history	See info



Registration #1	2012-03-27	23 mi
Registration #2	2015-02-28	24.558 mi
Registration #3	2016-03-22	33.990 mi
Registration #4	2017-03-25	39.530 mi
Registration #5	2018-03-27	40.891 mi
Registration #6	2019-03-27	42.972 mi
Registration #7	2019-03-28	42.972 mi
Registration #8	2020-02-20	45.911 mi
Registration #9	2020-03-27	46.377 mi
Registration #10	2020-03-27	46.377 mi
Registration #11	2020-03-27	46.377 mi
Registration #12	2020-03-27	46.377 mi
Registration #13	2020-03-27	46.377 mi
Registration #14	2020-03-27	46.377 mi
Registration #15	2020-03-27	46.377 mi
Registration #16	2020-03-27	46.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	0054800