



**DG58SHX**

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Grey
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-12
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	23
Total items failed	4

MOT #22	2023-10-11 12:43
MOT test number	504338959480
Result	✓ Passed
Next expiry date	2024-10-12

MOT #21	2023-10-10 11:00
MOT test number	963475029162
Result	✗ Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #20	2022-10-13 16:03
MOT test number	484541905899
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2022-10-03 15:21**MOT test number** 911544991922**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**MOT #18** 2021-09-15 10:23**MOT test number** 994442301727**Result** ✓ Passed**MOT #17** 2021-09-14 16:20**MOT test number** 466510254081**Result** ✗ Failed**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #16** 2020-10-06 13:57**MOT test number** 655611891420**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material All (1.1.11 (c))

**MOT #15** 2019-10-07 14:58**MOT test number** 237316428705**Result** Passed**MOT #14** 2019-10-02 16:12**MOT test number** 584444899469**Result** Failed**DANGEROUS** Offside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #13** 2018-10-02 14:13**MOT test number** 858422157189**Result** Passed**MOT #12** 2018-10-01 15:52**MOT test number** 478133329983**Result** Failed**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2017-09-15 07:34**MOT test number** 399924403681**Result** Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both inner faces (3.5.1i)

**MOT #10** 2017-09-13 15:16**MOT test number** 410099145898**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both inner faces (3.5.1i)**Advice** Nearside Rear Tyre worn on edges and cracking between tread pattern**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #9** 2016-09-21 15:11**MOT test number** 794807644047**Result** ✓ Passed**MOT #8** 2016-09-20 15:52**MOT test number** 520151538602**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #7** 2015-09-17 13:48**MOT test number** 772350608303**Result** ✓ Passed**MOT #6** 2014-09-22 16:51**MOT test number** 479095764292**Result** ✓ Passed**Notice** N/s mirror glass missing**MOT #5** 2013-08-28 14:26**MOT test number** 227820043295**Result** ✓ Passed



<b>MOT #4</b>	2013-08-28 14:26
---------------	------------------

<b>MOT test number</b>	926990943207
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Offside Headlamp aim too low (1.8)
--------------------------------	------------------------------------

<b>MOT #3</b>	2012-09-11 10:53
---------------	------------------

<b>MOT test number</b>	877415252292
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-09-11 10:53
---------------	------------------

<b>MOT test number</b>	326505652280
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Headlamp aim too high (1.8)
--------------------------------	--------------------------------------

<b>MOT #1</b>	2011-09-27 11:54
---------------	------------------

<b>MOT test number</b>	306510471487
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-10
Last registration	2023-10-11
Complete history	<a href="#">See info</a>



Registration #1	2008-09-10	29 mi
Registration #2	2011-09-27	28.728 mi
Registration #3	2012-09-11	36.100 mi
Registration #4	2013-08-28	43.510 mi
Registration #5	2014-09-22	51.902 mi
Registration #6	2015-09-17	69.697 mi
Registration #7	2016-09-20	88.197 mi
Registration #8	2016-09-21	88.215 mi
Registration #9	2017-09-13	94.917 mi
Registration #10	2017-09-15	94.936 mi
Registration #11	2018-10-01	99.115 mi
Registration #12	2019-09-27	103.300 mi
Registration #13	2020-09-27	107.485 mi
Registration #14	2021-09-27	111.670 mi
Registration #15	2022-09-27	115.855 mi
Registration #16	2023-09-27	120.040 mi
Registration #17	2024-09-27	124.225 mi
Registration #18	2025-09-27	128.410 mi
Registration #19	2026-09-27	132.595 mi
Registration #20	2027-09-27	136.780 mi
Registration #21	2028-09-27	140.965 mi
Registration #22	2029-09-27	145.150 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG