



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	VIANO CDI LONG AMBIENTE
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	440 Nm at 1.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	30.7 mpg
CO2 emission	244 g/km
CO2 label	L





Internet history

Entry 5

Date 2023-02-06

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 4

Date 2023-01-09

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 3

Date 2022-12-12

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2022-11-14

Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-12-13
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	17
Total items failed	13

MOT #13	2023-11-22 17:13
MOT test number	328874915409
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material greased (1.1.11 (c))

**MOT #12**

2023-11-22 09:59

MOT test number

222639821669

Result**✗ Failed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Brake pipe corroded, covered in grease or other material greased (1.1.11 (c))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Fail** Horn not working (7.7 (a))
- Fail** Exhaust system insecure (6.1.2 (a))
- Fail** Nearside Front Service brake grabbing severely (1.2.1 (c))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

MOT #11

2022-12-14 15:39

MOT test number

263666131620

Result**✓ Passed****MOT #10**

2021-11-17 17:16

MOT test number

575768590523

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2020-11-12 16:26

MOT test number

317854252904

Result**✓ Passed**

**MOT #8** 2020-11-12 16:26**MOT test number** 912503454845**Result** ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #7 2019-10-04 15:29**MOT test number** 321734318433**Result** ✓ Passed

Advice Brake pedal anti-slip splitting.

Advice Unable to open bonnet by normal way.

MOT #6 2019-10-04 15:29**MOT test number** 863737779636**Result** ✗ Failed

Pass with rectification Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

Advice Unable to open bonnet by normal way.

Pass with rectification Nearside Front Headlamp aim too high and too far to the right. (4.1.2 (a))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively Both. (3.4 (b) (ii))

Advice Brake pedal anti-slip splitting.

MOT #5 2018-10-18 15:19**MOT test number** 135007057101**Result** ✓ Passed**MOT #4** 2018-01-15 13:36**MOT test number** 407203339979**Result** ✓ Passed

**MOT #3** 2017-01-20 14:53**MOT test number** 816281312460**Result** ✓ Passed**Advice** Rear shockers soft**MOT #2** 2011-08-11 16:19**MOT test number** 956543721217**Result** ✓ Passed**MOT #1** 2011-08-11 10:23**MOT test number** 187713121298**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** O/s/rear snow and mud type tyre not recommend,n/s/front steering arm worn,**Fail** Offside Front Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 SN08OMC
Plate since	2024-03-28
Current registration	 SN08OMC
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-12
Last registration	2023-11-22
Complete history	See info



Registration #1	2008-03-12	13 mi
Registration #2	2011-08-11	98.529 mi
Registration #3	2011-08-11	98.583 mi
Registration #4	2017-01-20	123.477 mi
Registration #5	2018-01-15	126.082 mi
Registration #6	2018-10-18	127.479 mi
Registration #7	2019-10-04	132.497 mi
Registration #8	2019-10-04	132.497 mi
Registration #9	2020-11-12	137.577 mi
Registration #10	2020-11-12	137.577 mi
Registration #11	2020-11-12	137.577 mi
Registration #12	2020-11-12	137.577 mi
Registration #13	2020-11-12	137.577 mi
Registration #14	2020-11-12	137.577 mi
Registration #15	2020-11-12	137.577 mi
Registration #16	2020-11-12	137.577 mi
Registration #17	2020-11-12	137.577 mi
Registration #18	2020-11-12	137.577 mi
Registration #19	2020-11-12	137.577 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1901 mm
Height	1875 mm
Length	4993 mm
Wheel base	3200 mm

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	64299040652912