





report date: 2024-03-29

General information

| Make | NISSAN |
|---------------------|------------------------------|
| Model | NAVARA DCI TEKNA 4X4 SHR DCB |
| Colour | Black |
| Year of manufacture | 2018 |
| Top speed | 114 mph |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 450 Nm at 2.500 rpm |
| Engine capacity | 2.298 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 41.0 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 44.9 mpg |
| CO2 emission | 167 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/10



Internet history

Entry 1

Date 2021-11-26

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2023-12-07 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 3 |

| MOT #3 | 2022-12-08 12:58 |
|---|--------------------------------|
| MOT test number | 148687071802 |
| Result | ✓ Passed |
| Next expiry date | 2023-12-07 |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamp (i)) | os or light sources (4.7.1 (b) |

| MOT #2 | 2022-12-05 16:45 |
|--|--------------------|
| MOT test number | 995692427506 |
| Result | × Failed |
| Fail Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting (a) (ii)) | ng surface (4.8.1 |
| Fail Offside Rear Stop lamp(s) lens defective such that the emitted light is adversely aff (ii)) | fected (4.3.1 (b) |
| Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i)) | sources (4.7.1 (b) |
| Advice Offside Rear light unit damaged | |
| Fail Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii)) | |

| MOT #1 | 2021-11-12 16:31 |
|--|------------------|
| MOT test number | 544321295436 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/10



Tax & MOT check





| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 215 |
| MOT expiry date | 7 December 2023 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|-------------|
| | |
| HARMAN CO. C. | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | NIK NIK |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2018-10-31 |
| Last registration | 2022-12-08 |
| Complete history | See info |



| Registration #1 | 2018-10-31 | 8 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-11-12 | 86.180 mi |
| Registration #3 | | 11.177 es |
| Registration #4 | | 77,777 46 |
| Registration #5 | | 9.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 78% |
| Pedestrian | 78% |
| Safety systems | 68% |
| Overall rating | 76% |
| Video | see crash video |



Dimensions & weight

| Width | 2085 mm |
|---------------------|---------|
| Height | 1825 mm |
| Length | 5330 mm |
| Kerb weight | 1998 kg |
| Max. allowed weight | 3045 kg |

Additional information

| Fuel tank capacity | 73 |
|---------------------------------|--------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Engine number CarCheck.co.uk | 035615C page 10/10 |