



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MERIVA EXCLUSIV AC CDTI
Colour	Silver
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	108 BHP
Max. torque	280 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-19
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #10	2023-06-26 08:49
MOT test number	414174993088
Result	✓ Passed
Next expiry date	2024-06-29

MOT #9	2022-06-21 08:51
MOT test number	673382001668
Result	✓ Passed

MOT #8	2021-06-30 11:36
MOT test number	287682010563
Result	✓ Passed

MOT #7	2021-06-22 14:05
MOT test number	691028721172
Result	✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2021-02-09 17:25**MOT test number** 977787432198**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2020-01-18 08:56**MOT test number** 153244618701**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-02-09 12:26**MOT test number** 460305393502**Result** ✓ Passed**MOT #3** 2019-02-01 12:02**MOT test number** 267950265846**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #2** 2018-01-23 15:52**MOT test number** 752490126512**Result** ✓ Passed



MOT #1	2017-02-08 11:43
MOT test number	562114102183
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	PF63ZYE
Plate since	2019-03-29
Current registration	PF63ZYE
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-02-13
Last registration	2023-06-26
Complete history	See info



Registration #1	2014-02-13	12 mi
Registration #2	2017-02-08	12.324 mi
Registration #3	2018-01-23	17.595 mi
Registration #4	2019-02-01	31.551 mi
Registration #5	2019-02-09	32.017 mi
Registration #6	2020-01-18	43.800 mi
Registration #7	2020-06-26	55.277 mi
Registration #8	2021-06-26	66.754 mi
Registration #9	2022-06-26	78.231 mi
Registration #10	2023-06-26	89.708 mi
Registration #11	2024-06-26	101.185 mi
Registration #12	2025-06-26	112.662 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1518 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	A17DTI - 2713877LPL