



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	CELICA T SPORT VVTI
Colour	Black
Year of manufacture	2003
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	179 Nm at 6.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J








Internet history

Entry 1

Date	2021-08-07
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-24
MOT pass rate	70 %
MOT passed	19
Failed MOT tests	8
Total advice items	32
Total items failed	26

MOT #27 2023-11-11 11:59

MOT test number 685238005991

Result ✓ Passed

Next expiry date 2024-11-24

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #26 2022-10-28 08:47

MOT test number 263547833276

Result ✓ Passed

MOT #25 2021-10-25 15:28

MOT test number 285061295031

Result ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear tyres slightly lumpy
- Advice** Nearside Rear tyres slightly lumpy

**MOT #24**

2021-10-25 11:16

MOT test number

731149778708

Result

✗ Failed

Advice Offside Rear tyres slightly lumpy**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Rear tyres slightly lumpy**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #23**

2020-11-17 11:08

MOT test number

251610106442

Result

✓ Passed

Advice General surface corrosion apparent on all components and prescribed areas under the vehicle**Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #22**

2019-11-25 11:28

MOT test number

706446475601

Result

✓ Passed

MOT #21

2018-11-21 10:29

MOT test number

235252798308

Result

✓ Passed

Advice Headlamp lenses slightly deteriorated**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2018-11-20 09:50

MOT test number

527270282353

Result

✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Road wheel fixing missing wheel nut (5.2.1 (a) (i))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Headlamp lenses slightly deteriorated
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Road wheel fixing missing wheel nut (5.2.1 (a) (i))

MOT #19

2017-11-16 10:45

MOT test number

364847875774

Result

✓ Passed

- Advice** Offside Front tyre inner & outer sidewall cracking
- Advice** Engine management light on

MOT #18

2016-10-25 12:08

MOT test number

701105088082

Result

✓ Passed

**MOT #17** 2015-11-17 09:43**MOT test number** 665698997320**Result** ✓ Passed**MOT #16** 2015-11-17 09:43**MOT test number** 656201629436**Result** ✗ Failed

- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #15 2014-09-23 18:46**MOT test number** 475826864220**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components

MOT #14 2013-10-01 17:27**MOT test number** 396274673216**Result** ✓ Passed

- Notice** Oil leak

**MOT #13**

2013-09-26 17:01

MOT test number

576659363288

Result**✗ Failed****Fail**

Nearside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)

Fail

Offside Front Tie bar/rod rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)

Fail

Offside Rear Registration plate lamp not working (1.1.C.1d)

Notice

Oil leak

Fail

Offside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)

Fail

Nearside Front Tie bar/rod rubber mounting bonding deteriorated resulting in excessive movement (2.4.G.2)

Fail

Offside Front Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #12

2012-04-26 14:55

MOT test number

359277712140

Result**✓ Passed****MOT #11**

2011-05-14 10:30

MOT test number

278884831126

Result**✓ Passed****MOT #10**

2011-05-14 10:30

MOT test number

877874331132

Result**✗ Failed****Pass with rectification**

Offside Stop lamp not working (1.2.1b)

**MOT #9** 2010-05-22 11:48**MOT test number** 361292340174**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2010-05-22 11:48**MOT test number** 740862440159**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2009-03-04 10:06**MOT test number** 711133669027**Result** ✓ Passed**MOT #6** 2008-03-07 14:56**MOT test number** 174097568023**Result** ✓ Passed**MOT #5** 2008-03-07 10:59**MOT test number** 480327968047**Result** ✗ Failed**Fail** Offside Front Headlamp aim too low (1.8)**Advice** Front brake disc slightly scored (3.5.1h)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2007-05-19 12:54**MOT test number** 210899637463**Result** ✓ Passed**MOT #3** 2007-05-18 14:47**MOT test number** 270918737172**Result** ✗ Failed**Advice** Front brake disc slightly scored (3.5.1h)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear brake disc slightly scored (3.5.1h)**MOT #2** 2006-04-11 17:04**MOT test number** 200121406141**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-02-03 15:38**MOT test number** 663524736028**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
24 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-03-01
Last registration	2023-11-11
Complete history	See info



Registration #1	2003-03-01	9 mi
Registration #2	2006-02-03	52.253 mi
Registration #3	2006-04-11	53.656 mi
Registration #4	2007-05-18	60.880 mi
Registration #5	2007-05-19	60.902 mi
Registration #6	2008-03-07	66.809 mi
Registration #7	2008-03-07	66.809 mi
Registration #8	2009-03-04	70.822 mi
Registration #9	2010-05-22	75.166 mi
Registration #10	2011-05-14	78.569 mi
Registration #11	2012-04-26	82.137 mi
Registration #12	2013-09-26	84.942 mi
Registration #13	2013-10-01	84.942 mi
Registration #14	2014-09-23	84.998 mi
Registration #15	2015-05-20	85.277 mi
Registration #16	2016-05-20	85.277 mi
Registration #17	2016-05-20	85.277 mi
Registration #18	2016-05-20	85.277 mi
Registration #19	2016-05-20	85.277 mi
Registration #20	2016-05-20	85.277 mi
Registration #21	2016-05-20	85.277 mi
Registration #22	2016-05-20	85.277 mi
Registration #23	2016-05-20	85.277 mi
Registration #24	2016-05-20	85.277 mi
Registration #25	2016-05-20	85.277 mi
Registration #26	2016-05-20	85.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	2ZZ0115893