



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 ACTIVE
Colour	Red
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 2

Date	2021-07-01
Pictures	23
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-06-16
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	38
Total items failed	10

MOT #14	2024-04-05 13:18
---------	------------------

MOT test number	727346332007
-----------------	--------------

Result	✓ Passed
Next expiry date	2025-04-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1mm/2mm edges, 3mm centre and heavily perished (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 0mm/2mm edges, 3mm centre and heavily perished (5.2.3 (e))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning upper half of taillight not working (4.2.1 (a) (i))
Advice	Exhaust tailpipe heat shield loose
Advice	Brake pipe corroded, covered in grease or other material All underside brake pipes corroding (1.1.11 (c))

**MOT #13**

2024-04-05 11:56

MOT test number

631988631618

Result**✗ Failed**

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Exhaust tailpipe heat shield loose

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 0mm/2mm edges, 3mm centre and heavily perished (5.2.3 (e))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning upper half of taillight not working (4.2.1 (a) (i))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure perished full depth to cords (5.2.3 (d) (ii))

Advice Brake pipe corroded, covered in grease or other material All underside brake pipes corroding (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge 1mm/2mm edges, 3mm centre and heavily perished (5.2.3 (e))

MOT #12

2023-03-27 07:44

MOT test number

153573210267

Result**✓ Passed**

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2023-03-24 12:03

MOT test number

307289721102

Result**✗ Failed****Fail**

Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail

Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2022-03-30 11:08

MOT test number

607169529450

Result**✓ Passed****Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Splash guards / heat shields / engine covers / component covers obscuring some areas and or items

Advice

Tyre worn close to legal limit/worn on edge 3 tyres on 3mm: both front and os rear (5.2.3 (e))

Advice

Front Registration plate deteriorated but not likely to be misread damage / distorted (0.1 (b))

Advice

Light / minor corrosion to some underbody component

**MOT #9** 2022-03-17 13:39**MOT test number** 685137732134**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge 3 tyres on 3mm: both front and os rear (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread damage / distorted (0.1 (b))**Fail** Emissions not tested vehicle running on 3 cylinders and cuts out sporadically during idle (8.2.1.2 (d))**Advice** Splash guards / heat shields / engine covers / component covers obscuring some areas and or items**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Engine MIL inoperative or indicates a malfunction MIL on (8.2.1.2 (h))**Advice** Light / minor corrosion to some underbody component**MOT #8** 2021-03-04 15:36**MOT test number** 334810356737**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-03-03 13:28**MOT test number** 238640277616**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #6** 2020-03-11 11:33**MOT test number** 461233116553**Result** ✓ Passed

**MOT #5** 2019-02-21 16:49**MOT test number** 437778995409**Result** ✓ Passed**MOT #4** 2019-02-21 14:46**MOT test number** 348764384241**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #3** 2018-03-13 15:00**MOT test number** 504099921928**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2018-03-12 09:22**MOT test number** 193984208350**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2017-03-13 14:41**MOT test number** 757968667373**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2014-03-21
Last registration	2024-04-05
Complete history	See info



Registration #1	2014-03-21	23 mi
Registration #2	2017-03-13	27.929 mi
Registration #3	2018-03-12	40.466 mi
Registration #4	2018-03-13	40.466 mi
Registration #5	2019-02-21	55.422 mi
Registration #6	2019-02-21	55.422 mi
Registration #7	2020-03-11	68.363 mi
Registration #8	2021-03-03	79.091 mi
Registration #9	2021-03-04	79.101 mi
Registration #10	2022-03-03	91.377 mi
Registration #11	2022-03-03	91.377 mi
Registration #12	2022-03-03	91.377 mi
Registration #13	2022-03-03	91.377 mi
Registration #14	2022-03-03	91.377 mi
Registration #15	2022-03-03	91.377 mi
Registration #16	2022-03-03	91.377 mi
Registration #17	2022-03-03	91.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LADM174143