




report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Blue
Year of manufacture	2012
Top speed	93 mph
0 - 60 mph	17.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	C





MOT history

MOT expiry date	2024-07-31
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #10	2023-08-01 12:24
MOT test number	716708932812
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Offside Rear brake lagging slightly
Advice	Brake pipe corroded, covered in grease or other material both front to rear at rear (1.1.11 (c))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9	2022-07-18 10:35
MOT test number	712493193809
Result	✓ Passed

MOT #8	2021-07-19 10:23
MOT test number	563919986529
Result	✓ Passed

MOT #7	2020-07-23 13:26
MOT test number	247710531156
Result	✓ Passed



MOT #6	2019-06-25 14:43
MOT test number	155213227875
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Both rear tyres perished on sidewalls

MOT #5	2019-06-25 14:42
MOT test number	886276576443
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Both rear tyres perished on sidewalls
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #4	2018-06-29 14:32
MOT test number	948006196867
Result	✓ Passed
Minor	Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (i))

MOT #3	2017-06-30 13:48
MOT test number	149469714100
Result	✓ Passed

MOT #2	2016-06-27 13:59
MOT test number	546619866632
Result	✓ Passed



MOT #1	2015-06-30 14:53
MOT test number	409801885164
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
31 July 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	YE12ESV
Plate since	2019-09-29
Current registration	YE12ESV
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled. If not, and you buy this SUZUKI then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-06-30
Last registration	2023-08-01
Complete history	See info



Registration #1	2012-06-30	21 mi
Registration #2	2015-06-30	11.141 mi
Registration #3	2016-06-27	13.769 mi
Registration #4	2017-06-30	16.768 mi
Registration #5	2018-06-29	18.428 mi
Registration #6	2019-06-25	19.852 mi
Registration #7	2020-06-25	21.277 mi
Registration #8	2021-06-25	22.702 mi
Registration #9	2022-06-25	24.127 mi
Registration #10	2023-06-25	25.552 mi
Registration #11	2023-08-01	26.977 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	970 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1547602