





report date: 2024-03-28

General information

Make	BMW
Model	123 118D M SPORT
Colour	Black
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-07

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

 Date
 2021-10-06

 Pictures
 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-18
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #15		2024-04-19 09:19
MOT test	number	652606885572
Result		✓ Passed
Next expi	ry date	2025-04-18
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2023-04-13 11:38
MOT test number	709847372933
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2022-04-09 11:07
MOT test number	905698062766
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	

MOT #12	2021-04-16 12:53
MOT test number	312705673000
Result	✓ Passed

CarCheck.co.uk page 3/13



Passed

MOT #11 2020-08-05 12:58

MOT test number 629955943251

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Nearside and Offside brake disc corroded

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Nearside and Offside brake disc wearing low

MOT #10 2019-08-17 09:32

MOT test number 261255069435

Result \rightarrow Passed

Advice Front Nearside and Offside brake disc corroded

MOT #9 2018-08-04 14:20

MOT test number 836045719252

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

Advice Offside Rear Nail in tyre

Result

MOT #8 2017-08-23 15:21

MOT test number 977769694732

Result ✓ Passed

MOT #7 2016-08-10 12:21

MOT test number 814611538791

CarCheck.co.uk page 4/13



MOT #6 2016-07-30 11:11

MOT test number 243361049240

Result × Failed

Fail Offside Rear brake caliper locking device missing (3.5.1l)

Advice Front Nearside and Offside tyres have the tread cracked

MOT #5 2015-08-11 12:46

MOT test number 916503625281

Result ✓ Passed

MOT #4 2014-09-24 12:50

MOT test number 669537264268

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

MOT #3 2013-09-20 15:55

MOT test number 258033463215

Result ✓ Passed

MOT #2 2013-03-21 12:28

MOT test number 896180483021

Notice O/s/r tyre wearing on inner edge

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

815673192035

Result

Notice Nail in nearside rear tyre

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

obser of plates

funda scincos

M27MSN

report date: 2024-03-28

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

.....

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-08-17
Last registration	2024-04-19
Complete history	See info



Registration #1	2009-08-17	16 mi
Registration #2	2012-04-02	14.747 mi
Registration #3	2013-03-21	23.221 mi
Registration #4	2013-09-20	27.498 mi
Registration #5	2014-09-24	32.047 mi
Registration #6	2015-08-11	35.392 mi
Registration #7	2016-07-30	38.723 mi
Registration #8	2016-08-10	38.848 mi
Registration #9	2017-08-23	42.549 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1748 mm
Height	1411 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1500 kg
Max. allowed weight	1940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 13/1