





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	I800 CRDI SE
Colour	Black
Year of manufacture	2016
Top speed	104 mph
0 - 60 mph	17.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	134 BHP
Max. torque	343 Nm at 1.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	197 g/km
CO2 label	J



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

### Entry 1

Date 2022-01-04

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2025-01-20
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #8		2024-01-13 13:44
MOT test	number	529549799597
Result		✓ Passed
Next expi	ry date	2025-01-20
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5	5.2.3 (d) (i))
Advice	Nearside Child Seat fitted not allowing full inspection of adult belt 2nd row	
Advice	Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #7		2023-01-14 09:51
MOT test	number	947520643444
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #6	2022-01-21 16:48
MOT test number	453322795181
Result	✓ Passed
MOT #5	2021-06-09 17:44
MOT test number	921022837842
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

**AP16WCN** 

report date: 2024-03-28

× Failed

MOT #4 2021-05-11 11:28

**MOT test number** 847446384949

**Result** X Failed

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #3 2020-04-25 15:04

**MOT test number** 543543880114

**Result** ✓ Passed

MOT #2 2020-04-25 14:18

MOT test number 288755265637

**Result** X Failed

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2020-04-24 07:46

**MOT test number** 675442718075

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	20 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full in		NDAI
********		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-22
Last registration	2024-01-13
Complete history	See info



Registration #1	2016-07-22	11 mi
Registration #2	2020-04-24	29.705 mi
Registration #3	2020-04-25	29.705 mi
Registration #4	2020-04-25	29.705 mi
Registration #5	2021-05-11	33.035 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
		11.777 es 11.777 es
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



## Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5150 mm
Wheel base	3200 mm
Kerb weight	2294 kg
Max. allowed weight	3070 kg

## Additional information

Fuel tank capacity	75 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	8	page 11/11

Number of axles 2

**Engine number** D4CBG021173