



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	Silver
Year of manufacture	2014
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	21
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-02-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	23
Total items failed	7

MOT #11	2024-01-29 08:59
MOT test number	113640550991
Result	✓ Passed
Next expiry date	2025-02-04
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear differential slightly leaking
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10	2024-01-29 08:59
MOT test number	675438142189
Result	✗ Failed
Advice	Rear differential slightly leaking
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #9	2023-01-30 09:09
MOT test number	798893134253
Result	✓ Passed
Advice	Oil leak, but not excessive Rear Diff (8.4.1 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8	2023-01-27 09:58
MOT test number	268463503742
Result	✗ Failed
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
Advice	Oil leak, but not excessive Rear Diff (8.4.1 (a) (i))
Fail	Brake performance not tested (1.2.1 (g))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2022-01-27 11:05
MOT test number	372139799105
Result	✓ Passed
Advice	Rear differential leaking

MOT #6	2021-02-05 12:25
MOT test number	668849955604
Result	✓ Passed

**MOT #5** 2020-08-28 10:06**MOT test number** 646234072949**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner wear (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner wear (5.2.3 (e))**MOT #4** 2019-08-14 11:41**MOT test number** 736543475332**Result** ✓ Passed**MOT #3** 2019-08-10 09:16**MOT test number** 411053203519**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #2** 2018-08-17 09:20**MOT test number** 463204381719**Result** ✓ Passed**MOT #1** 2017-08-23 14:06**MOT test number** 170098893540**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2020-01-01
Current registration	XXXX XX
Plate since	2020-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-01
Last registration	2024-01-29
Complete history	See info



Registration #1	2014-09-01	27 mi
Registration #2	2017-08-23	27.472 mi
Registration #3	2018-08-17	38.964 mi
Registration #4	2019-08-10	53.773 mi
Registration #5	2019-08-14	53.794 mi
Registration #6	2020-08-28	65.542 mi
Registration #7	2020-08-28	65.542 mi
Registration #8	2020-08-28	65.542 mi
Registration #9	2020-08-28	65.542 mi
Registration #10	2020-08-28	65.542 mi
Registration #11	2020-08-28	65.542 mi
Registration #12	2020-08-28	65.542 mi
Registration #13	2020-08-28	65.542 mi
Registration #14	2020-08-28	65.542 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1535 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1135 kg
Max. allowed weight	1560 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1780561