





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Black
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-24


Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-02-12
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	28
Total items failed	4

MOT #14		2024-02-01 13:04
MOT test r	number	214559423920
Result		✓ Passed
Next expir	y date	2025-02-12
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear offside and nearside tyres perished	
Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))		
Advice	Underbody has surface rust	

MOT #13	2023-02-13 11:43
MOT test number	131076840268
Result	✓ Passed
Advice Rear Suspension arm pin or bush worn but not resulting in excession trailing arm (5.3.4 (a) (i))	ve movement o/s and n/s

MOT #12	2022-01-28 11:30
MOT test number	933557374044
Result	√ Passed

CarCheck.co.uk page 3/13



Fail

Advice

J44YDM report date: 2024-03-28

MOT #11

MOT test number

Result

Pass with rectification

Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #10 2021-02-06 12:02 **MOT** test number 594763457877 Result ✓ Passed **MOT** #9 2021-02-03 09:09 **MOT** test number 147944536753 Result × Failed Fail Road wheel fixing missing 1 missing of each wheel 4x in total (5.2.1 (a) (i)) **Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #8 2019-05-29 10:01
MOT test number 797504665739

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Result
✓ Passed

MOT #7 2018-05-30 10:20 MOT test number 378732322922

Advice Engine bay covers and undertrays fitted

Advice Offside repeater lens missing

CarCheck.co.uk page 4/13



MOT test number

Result

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Engine bay covers and undertrays fitted

Advice Offside indicator repeater lens/cover missing

2016-06-25 15:03 **MOT #5 MOT** test number 280377569883 Result ✓ Passed **Advice** Offside Rear tyre has minor cracking Advice Nearside Rear tyre valve deteriorated Advice Nearside Front lower arm rear bush deteriorated Advice Nearside Rear tyre has minor cracking Advice Nearside Front tyre valve deteriorated Advice Offside Front side repeater lens damaged **Advice** Offside Front lower arm rear bush deteriorated

MOT #4		2015-06-26 11:21
MOT test	number	439797375174
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Passenger seat(s) missing at time of test	
Notice	Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 5/13



MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Notice Passenger seat(s) missing at time of test

MOT #2		2014-06-17 11:50
MOT test	number	758448664198
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Passenger seat(s) missing at time of test	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #1	2013-06-18 12:03
MOT test number	976649663158
Result	✓ Passed

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	la : a b a .a
UWNER	INISTATV
OWITCH	THISCOLV

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NIE Zas UK
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-06-28
Last registration	2024-02-01
Complete history	See info



Registration #1	2010-06-28	6 mi
Registration #2	2013-06-18	22.633 mi
Registration #3	2014-06-17	30.215 mi
Registration #4	2015-06-19	37.417 mi
Registration #5	2015-06-26	37.565 mi
Registration #6	2016-06-25	43.981 mi
Registration #7	2017-06-02	49.727 mi
Registration #8	2018-05-30	52.924 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1733 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 13/13