



report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | MAZDA |
| Model | MX-5 I ROADSTER SE |
| Colour | Red |
| Year of manufacture | 2012 |
| Top speed | 121 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 124 BHP |
| Max. torque | 167 Nm at 4.500 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.8 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 167 g/km |
| CO2 label | H |






Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-02-24 |
| Pictures | 28 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-01 |
| Pictures | 0 |
| Listing price | View report |

source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-04-28 |
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 16 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #10 | 2023-04-29 08:54 |
| MOT test number | 547709358851 |
| Result | ✓ Passed |
| Next expiry date | 2024-04-28 |
| Advice | Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |

| | |
|-----------------|--|
| MOT #9 | 2022-04-26 16:02 |
| MOT test number | 985609782028 |
| Result | ✓ Passed |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |

| | |
|-----------------|--|
| MOT #8 | 2022-04-26 09:07 |
| MOT test number | 118395123658 |
| Result | ✗ Failed |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| DANGEROUS | Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #7 | 2021-03-12 11:21 |
| MOT test number | 608436648083 |
| Result | ✓ Passed |

**MOT #6** 2020-05-29 07:40**MOT test number** 227124743455**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Lamp damaged but not affecting operation**MOT #5** 2019-09-13 09:22**MOT test number** 297650505708**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #4** 2018-08-20 09:59**MOT test number** 677097824868**Result** ✓ Passed**MOT #3** 2017-08-08 13:01**MOT test number** 765294935066**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #2 | 2016-08-22 13:58 |
| MOT test number | 632953818018 |
| Result | ✓ Passed |
| Advice | Both rear tyres has cracks in the treads. |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Both front tyres has cracks in the treads. |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #1 | 2015-08-17 14:40 |
| MOT test number | 718607483341 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
28 April 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 March |
| Days left | | 306 |
| MOT expiry date | | 28 April 2024 |
| Full MOT history | | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2012-09-01 |
| Last registration | 2023-04-29 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2012-09-01 | 11 mi |
| Registration #2 | 2015-08-17 | 27.691 mi |
| Registration #3 | 2016-08-22 | 41.868 mi |
| Registration #4 | 2017-08-08 | 50.984 mi |
| Registration #5 | 2018-08-20 | 59.569 mi |
| Registration #6 | 2019-09-13 | 66.488 mi |
| Registration #7 | 2020-05-29 | 69.011 mi |
| Registration #8 | 2021-05-29 | 75.277 mi |
| Registration #9 | 2022-05-29 | 81.543 mi |
| Registration #10 | 2023-05-29 | 87.809 mi |
| Registration #11 | 2024-05-29 | 94.075 mi |
| Registration #12 | 2025-05-29 | 100.341 mi |
| Registration #13 | 2026-05-29 | 106.607 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1720 mm |
| Height | 1245 mm |
| Length | 4020 mm |
| Wheel base | 2330 mm |
| Kerb weight | 1150 kg |
| Max. allowed weight | 1375 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | L8 10237007 |