

Ford



General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	184 g/km
CO2 label	I







Internet history	
Entry 1	
Date	2021-01-30
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-08
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #13		2024-04-09 13:10
MOT test	number	560418152709
Result		✓ Passed
Next expiry date 2025-04-0		2025-04-08
Advice	Nearside Headlamp has a product on the lens but not seriously reducir	ng light output (4.1.4 (b))
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #12	2024-04-08 12:21
MOT test number	729544124158
Result	× Failed
Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4	4 (a) (i))
Fail Offside Front Tyre has a tear, caused by separation or partial failure of its str	ructure (5.2.3 (d) (ii))
Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its s	structure (5.2.3 (d) (ii))
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Nearside Headlamp has a product on the lens but not seriously reducing	light output (4.1.4 (b))





MOT #11		2023-03-10 11:40
MOT test	number	544284164349
Result		✓ Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in ex	cessive movement (5.3.4
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4 (a)

MOT #10	2022-03-03 15:03
MOT test number	759238317300
Result	✓ Passed

МОТ #9	2021-04-01 13:56
MOT test number	666101014377
Result	✓ Passed

MOT #	8	2021-03-30 12:17
MOT te	est number	828387248123
Result		🗙 Failed
Fail	Offside Front Service brake excessively fluctuating (1.2.1 (e))	
Fail	Nearside Front Service brake excessively fluctuating (1.2.1 (e))	

МОТ #7	2019-11-08 10:05
MOT test number	110528548134
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing no cords at tin	ne of test (5.2.3 (d) (ii))
Advice Offside Front Suspension arm pin or bush worn but not resulting in excess (5.3.4 (a) (i))	sive movement rear
Advice Nearside Front Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement rear





MOT #6		2018-11-19 11:51
MOT test	number	866602490472
Result		✓ Passed
Advice	Offside Rear Tyre starting to crack and perish. 205/55/16	
MOT #5		2017-11-20 09:48
MOT test	number	771146451907
Result		✓ Passed
Advice	Nearside Front Wiper smearing but clears screen	
Advice	Nearside Rear Tyre cracking on sidewall but not deep enough to reach cords	
Advice	Nearside Front Tyre starting to crack and perish on outer edge	
Advice	Offside Front Wiper smearing but clears screen	
Advice	Offside Rear Tyre cracking on sidewall but not deep enough to reach cords	

MOT #4	2016-11-25 13:51
MOT test number	165220799533
Result	✓ Passed
Advice Offside Rear Nail in tyre	

MOT #3	2015-11-30 15:12
MOT test number	517949791288
Result	✓ Passed
MOT #2	2013-08-31 09:44

MOT test number	786163343294
Result	✓ Passed





MOT #1	2013-02-27 14:07
MOT test number	769288653086
Result	✓ Passed



Tax & MOT check

✓ Taxed	√ MOT
Tax due: 1 June 2024	Expires: 8 April 2025
Tax status	Valid until 1 June
Days left	34
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-01-21
Last registration	2024-04-09
Complete history	<u>See info</u>



Registration #1	2010-01-21	9 mi
Registration #2	2013-02-27	7.892 mi
Registration #3	2013-08-31	8.586 mi
Registration #4	2015-11-30	20.178 mi
Registration #5	2016-11-25	32.224 mi
Registration #6	2017-11-20	36.322 mi
Registration #7	2018-11-19	43.935 mi
Registration #8	2019-11-08	59.339 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	AY19587