



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Silver
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-24
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #12	2023-10-18 15:29
MOT test number	949944215740
Result	✓ Passed
Next expiry date	2024-10-26
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 235/45 17 (5.2.3 (e))
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11	2022-10-20 09:35
MOT test number	793310129546
Result	✓ Passed
Minor	Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10	2021-10-20 11:17
MOT test number	810184176743
Result	✓ Passed

MOT #9	2020-10-20 14:11
MOT test number	368013229789
Result	✓ Passed

**MOT #8** 2019-04-01 10:58**MOT test number** 806405273353**Result** ✓ Passed**MOT #7** 2018-04-27 09:26**MOT test number** 474800776151**Result** ✓ Passed**MOT #6** 2016-11-15 09:31**MOT test number** 563300151185**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Nearside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)**MOT #5** 2015-11-19 15:31**MOT test number** 606243330522**Result** ✓ Passed**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-11-19 14:51**MOT test number** 915666647895**Result** ✗ Failed

Advice Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #3 2014-11-07 15:17**MOT test number** 265921014350**Result** ✓ Passed

Notice Nail in offside rear tyre

MOT #2 2013-11-05 10:23**MOT test number** 719689303398**Result** ✓ Passed

Advice Nearside Rear Direction indicators has light sources not illuminating, but not more than 50% (1.4.A.2c)

Advice Offside Rear Direction indicators has light sources not illuminating, but not more than 50% (1.4.A.2c)

MOT #1 2012-11-06 11:31**MOT test number** 205681512381**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KM59NUO
Plate since	2019-06-29
Current registration	 KM59NUO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-11-18
Last registration	2023-10-18
Complete history	See info



Registration #1	2009-11-18	8 mi
Registration #2	2012-11-06	30.749 mi
Registration #3	2013-11-05	35.672 mi
Registration #4	2014-11-07	42.287 mi
Registration #5	2015-11-19	47.025 mi
Registration #6	2015-11-19	47.025 mi
Registration #7	2016-11-15	52.446 mi
Registration #8	2019-10-20	55.277 mi
Registration #9	2019-10-20	55.277 mi
Registration #10	2019-10-20	55.277 mi
Registration #11	2019-10-20	55.277 mi
Registration #12	2019-10-20	55.277 mi
Registration #13	2019-10-20	55.277 mi
Registration #14	2019-10-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1510 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBA 174034