





report date: 2024-03-28

#### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TCE
Colour	Black
Year of manufacture	2009
Top speed	142 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	180 BHP
Max. torque	300 Nm at 2.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.7 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/14



report date: 2024-03-28

### Internet history

_		•		_	-
-	n	т	rv	,	

Lifety 1	
Date	2021-09-25
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT histo	orv
-----------	-----

MOT expiry date	2024-09-30
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	31
Total items failed	8

MOT #20	2023-09-11 13:05
MOT test number	973493799907
Result	<b>✓</b> Passed
Next expiry date	2024-09-30

MOT #19	2022-09-29 12:27
MOT test number	655320475845
Result	<b>✓</b> Passed

MOT #18	2022-09-28 12:50
MOT test number	727483149520
Result	<b>×</b> Failed

**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**MAJOR** Rear Brake disc significantly and obviously worn x2 (1.1.14 (a) (i))

MOT #17	2021-10-01 11:14
MOT test number	672255162178
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #16** 2021-10-01 11:14

**MOT test number** 258761257814

**Result** X Failed

Pass with rectification

Nearside Registration plate lamp inoperative in the case of a single lamp or all

lamps (4.7.1 (b) (ii))

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #15** 2021-02-10 14:33

MOT test number 741408845746

Result 

Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2021-02-10 14:33

**MOT test number** 790827241909

**Result** X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2020-02-11 12:12

MOT test number 161019465618

**Result** ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



**MAJOR** 

Fail

FD580MG

report date: 2024-03-28

MOT test number

Result

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT test number

Result

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2018-02-02 16:43

MOT test number 639200941567

Result ✓ Passed

MOT #9

MOT test number

Result

Rear registration plate character(s) incorrectly spaced (6.3.4a)

Fail Front registration plate character(s) incorrectly spaced (6.3.4a)

 MOT #8
 2017-02-07 10:29

 MOT test number
 437891880617

 Result
 ✓ Passed

Offside Front Front constant velocity joint is insecure (2.5.C.1b)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

568166135090

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #5
 2014-01-25 11:54

 MOT test number
 897395924048

 Result
 ✓ Passed

MOT #4

MOT test number

Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

528617933051

Result

Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)


Advice


Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/14



report date: 2024-03-28





CarCheck.co.uk page 7/14



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	30 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

## FD580MG

report date: 2024-03-28

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT?	NAULT
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
***************************************	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

## Plate changes

More info >

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

### Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-20
Last registration	2023-09-11
Complete history	See info



Registration #1	2009-01-20	25 mi
Registration #2	2012-01-14	32.403 mi
Registration #3	2013-02-06	34.476 mi
Registration #4	2013-02-06	34.476 mi
Registration #5	2014-01-25	43.022 mi
Registration #6	2015-02-05	51.173 mi
Registration #7	2016-02-03	59.405 mi
Registration #8	2017-02-07	69.011 mi
Registration #9	2018-02-02	81.163 mi
Registration #10	2018-02-02	81.163 mi
Registration #11	2019-01-31	93.420 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		9.377 mi

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

S0225	Air conditionir
S0295	
50482	
50501	
60566	
50567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 14/1

**Engine number** 

C003212