




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Silver
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-12-13
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-31
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	24
Total items failed	12

MOT #20	2023-09-01 10:07
MOT test number	892726000916
Result	✓ Passed
Next expiry date	2024-08-31
Advice	Nearside Rear Nail in tyre Has 2 nails in it.
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19	2023-09-01 08:13
MOT test number	600781890566
Result	✗ Failed
Advice	Nearside Rear Nail in tyre Has 2 nails in it.
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #18**

2022-05-11 12:31

MOT test number

270397260734

Result

✓ Passed

Minor

Nearside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor

Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17

2021-03-03 14:55

MOT test number

272683374459

Result

✓ Passed

Advice

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Corrosion to rear suspension components

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice

Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #16** 2021-03-01 12:11**MOT test number** 472219846775**Result** ✗ Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Corrosion to rear suspension components

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15 2020-02-12 09:13**MOT test number** 562772305858**Result** ✓ Passed

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #14 2019-02-15 15:52**MOT test number** 579842465673**Result** ✓ Passed**MOT #13** 2019-02-15 10:14**MOT test number** 668306239140**Result** ✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2018-02-02 09:12**MOT test number** 694640075311**Result** ✓ Passed**MOT #11** 2018-02-02 09:12**MOT test number** 985944565540**Result** ✗ Failed**Pass with rectification** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #10** 2017-02-02 10:18**MOT test number** 264571694819**Result** ✓ Passed**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2017-02-02 10:18**MOT test number** 278664114940**Result** ✗ Failed**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-02-15 12:58**MOT test number** 942613812000**Result** ✓ Passed

**MOT #7** 2015-02-19 09:47**MOT test number** 627570355002**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-02-18 10:58**MOT test number** 126999844055**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2013-01-24 16:04**MOT test number** 898304323019**Result** ✓ Passed**MOT #4** 2012-02-23 08:42**MOT test number** 716104652053**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-02-23 08:55**MOT test number** 626594251000**Result** ✓ Passed**MOT #2** 2011-02-23 08:55**MOT test number** 577294751090**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the left (1.8)



MOT #1	2010-02-19 09:51
MOT test number	171530650479
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BP56DVM
Plate since	2024-03-28
Current registration	 BP56DVM
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-02-20
Last registration	2023-09-01
Complete history	See info



Registration #1	2007-02-20	25 mi
Registration #2	2010-02-19	19.465 mi
Registration #3	2011-02-23	24.534 mi
Registration #4	2012-02-23	26.006 mi
Registration #5	2013-01-24	26.789 mi
Registration #6	2014-02-18	34.143 mi
Registration #7	2015-02-19	42.838 mi
Registration #8	2016-02-15	50.886 mi
Registration #9	2017-02-02	57.141 mi
Registration #10	2017-02-02	57.141 mi
Registration #11	2018-02-02	60.023 mi
Registration #12	2019-02-02	60.023 mi
Registration #13	2020-02-02	60.023 mi
Registration #14	2021-02-02	60.023 mi
Registration #15	2022-02-02	60.023 mi
Registration #16	2023-02-02	60.023 mi
Registration #17	2024-02-02	60.023 mi
Registration #18	2025-02-02	60.023 mi
Registration #19	2026-02-02	60.023 mi
Registration #20	2027-02-02	60.023 mi
Registration #21	2028-02-02	60.023 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN