



General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-29
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	44
Total items failed	7

MOT #13	2023-09-28 08:03
MOT test number	317028802337
Result	✓ Passed
Next expiry date	2024-09-27

MOT #12	2022-07-06 09:21
MOT test number	307592978082
Result	✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm both (5.3.4 (a) (i))

**MOT #11**

2021-07-06 12:11

MOT test number

729897440228

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Exhaust mounting defective centre and rear (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10

2021-07-06 12:11

MOT test number

594105269197

Result

✗ Failed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Exhaust mounting defective centre and rear (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #9** 2020-07-03 09:57**MOT test number** 472292299561**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2019-07-01 11:33**MOT test number** 957619516560**Result** ✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2018-06-27 14:40**MOT test number** 605066702624**Result** ✓ Passed

- Advice** Engine bay covers fitted.
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Vehicle under trays fitted.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

**MOT #6** 2017-06-28 10:43**MOT test number** 218101259241**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Engine covers and under trays fitted to the vehicle**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #5** 2017-06-28 09:38**MOT test number** 689169984512**Result** ✗ Failed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Engine covers and under trays fitted to the vehicle**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2016-06-21 16:24**MOT test number** 387122237522**Result** ✓ Passed



MOT #3	2015-08-28 12:55
MOT test number	408007625903
Result	✓ Passed
Advice	Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear inner pads appear low

MOT #2	2014-08-21 14:15
MOT test number	776243934234
Result	✓ Passed
Notice	All 4 tyres close to limits

MOT #1	2013-08-23 09:58
MOT test number	236045333258
Result	✓ Passed
Notice	Both rear tyres wearing on inner edges



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RV60NMM
Plate since	2019-09-29
Current registration	RV60NMM
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-10
Last registration	2023-09-28
Complete history	See info



Registration #1	2010-09-10	21 mi
Registration #2	2013-08-23	28.553 mi
Registration #3	2014-08-21	40.414 mi
Registration #4	2015-08-28	51.085 mi
Registration #5	2016-06-21	59.273 mi
Registration #6	2017-06-28	73.130 mi
Registration #7	2017-06-28	73.139 mi
Registration #8	2018-06-27	87.645 mi
Registration #9	2019-06-27	95.277 mi
Registration #10	2020-06-27	102.277 mi
Registration #11	2021-06-27	109.277 mi
Registration #12	2022-06-27	116.277 mi
Registration #13	2023-06-27	123.277 mi
Registration #14	2024-06-27	130.277 mi
Registration #15	2025-06-27	137.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1500 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1587 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU19126