



General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Silver
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G






Internet history

Entry 2

Date	2021-09-14
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-13
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-15
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	31
Total items failed	0

MOT #152023-09-14 14:46

MOT test number487040766354

Result✓ Passed

Next expiry date2024-09-15

- Advice**Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor**Windscreen damaged but not adversely affecting driver's view Stone chips in screen (3.2 (a) (i))
- Advice**Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Minor**Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice**Nearside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice**Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice**Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor**Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice**Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**MOT #14**

2023-09-14 11:23

**MOT test number**

865960451448

**Result****✗ Failed**

- Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view Stone chips in screen (3.2 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit Smoke value 1.00 on sticker inside  
passengers front door (8.2.2.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**MOT #13**

2022-09-16 11:45

**MOT test number**

686733797042

**Result****✓ Passed****MOT #12**

2022-09-16 10:55

**MOT test number**

927455722335

**Result****✗ Failed**

- MAJOR** Exhaust emissions exceed manufacturer's specified limit Smoke limit 1.00 on chassis sticker  
inside passenger front door (8.2.2.2 (a))

**MOT #11** 2021-09-14 11:28**MOT test number** 835606609375**Result** ✓ Passed**MOT #10** 2021-01-05 12:39**MOT test number** 198973112209**Result** ✓ Passed**MOT #9** 2019-07-03 09:40**MOT test number** 270090304001**Result** ✓ Passed**MOT #8** 2018-06-27 14:59**MOT test number** 491372328274**Result** ✓ Passed**Advice** Front and rear discs corroded.**Advice** Offside Rear Suspension component pin or bush slightly worn osr track arms. (5.3.4 (a) (i))**Advice** Nearside Rear Suspension component pin or bush slightly worn nsr track arms. (5.3.4 (a) (i))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2017-06-30 13:05**MOT test number** 329983744131**Result** ✓ Passed**Advice** Sidewalls cracking on all four tyres**MOT #6** 2016-06-13 12:53**MOT test number** 282840229807**Result** ✓ Passed**Advice** Sidewalls on all four tyres cracking



MOT #5 2015-06-23 15:10

MOT test number 349474275157

Result ✓ Passed

MOT #4 2014-06-25 09:51

MOT test number 695846974116

Result ✓ Passed

**Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)

MOT #3 2013-06-26 15:20

MOT test number 738387573159

Result ✓ Passed

MOT #2 2012-06-27 14:42

MOT test number 229579072188

Result ✓ Passed

MOT #1 2011-06-08 16:20

MOT test number 369699451152

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-27
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2008-06-27	20 mi
Registration #2	2011-06-08	25.107 mi
Registration #3	2012-06-27	30.917 mi
Registration #4	2013-06-26	35.912 mi
Registration #5	2014-06-25	42.804 mi
Registration #6	2015-06-23	47.212 mi
Registration #7	2016-06-13	51.774 mi
Registration #8	2017-06-30	55.941 mi
Registration #9	2018-06-27	58.867 mi
Registration #10	2019-06-27	61.777 mi
Registration #11	2020-06-27	64.777 mi
Registration #12	2021-06-27	67.777 mi
Registration #13	2022-06-27	70.777 mi
Registration #14	2023-06-27	73.777 mi
Registration #15	2024-06-27	76.777 mi
Registration #16	2025-06-27	79.777 mi
Registration #17	2026-06-27	82.777 mi
Registration #18	2027-06-27	85.777 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE A27658