



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA S
Colour	Black
Year of manufacture	2002
Top speed	121 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-21
MOT pass rate	71 %
MOT passed	20
Failed MOT tests	8
Total advice items	42
Total items failed	19

MOT #282024-02-19 14:05

MOT test number474608188271

Result✓ Passed

Next expiry date2025-02-21

**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Front Integral body structure is corroded but structural rigidity is not significantly reduced  
Crossmember (6.1.1 (c) (i))

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #27**

2024-02-19 11:23

**MOT test number**

107785495349

**Result****✗ Failed**

- Fail** Rear Brake pad(s) less than 1.5 mm thick Both (1.1.13 (a) (ii))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Integral body structure is corroded but structural rigidity is not significantly reduced Crossmember (6.1.1 (c) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

**MOT #26**

2023-02-21 15:21

**MOT test number**

402538918602

**Result****✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #25**

2023-02-21 15:21

**MOT test number**

984418019954

**Result****✗ Failed**

- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #24**

2022-02-22 14:25

**MOT test number**

176066355362

**Result****✓ Passed**

**MOT #23** 2021-02-05 13:43**MOT test number** 287150504563**Result** ✓ Passed**MOT #22** 2020-02-01 09:17**MOT test number** 722021508276**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #21** 2020-02-01 09:17**MOT test number** 848628817552**Result** ✗ Failed

- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #20** 2019-02-07 09:24**MOT test number** 873035084307**Result** ✓ Passed

- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #19** 2018-02-08 10:19**MOT test number** 233886194046**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #18** 2017-02-09 12:09**MOT test number** 281397527954**Result** ✓ Passed**Advice** Rear Tyres Cracking**MOT #17** 2017-02-09 12:09**MOT test number** 982589913822**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Rear Tyres Cracking**MOT #16** 2016-01-07 12:44**MOT test number** 728211341559**Result** ✓ Passed**MOT #15** 2015-02-14 10:39**MOT test number** 198075545495**Result** ✓ Passed**MOT #14** 2014-02-14 16:36**MOT test number** 107065944093**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #13** 2013-02-21 11:35**MOT test number** 668162753057**Result** ✓ Passed**MOT #12** 2013-02-20 09:37**MOT test number** 698221953025**Result** ✗ Failed

- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)
- Fail** Offside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

**MOT #11** 2012-02-21 14:40**MOT test number** 519202052000**Result** ✓ Passed

- Advice** Nearside Front Lower Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #10** 2012-02-20 16:45**MOT test number** 146971452490**Result** ✗ Failed

- Fail** Emissions not tested (7.0)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Nearside Front Lower Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #9** 2011-02-18 15:43**MOT test number** 645359441050**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8** 2011-02-18 11:31**MOT test number** 758489841044**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2010-02-20 09:45**MOT test number** 800111550007**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2009-02-18 09:58**MOT test number** 831649349001**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2009-02-18 09:58**MOT test number** 503779049040**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2008-02-08 09:28**MOT test number** 504839238091**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2007-01-29 13:55**MOT test number** 742599927084**Result** ✓ Passed**MOT #2** 2006-01-09 18:06**MOT test number** 313419806038**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2005-08-31 10:53**MOT test number** 380133645207**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
21 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	21 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2002-08-28
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2002-08-28	7 mi
Registration #2	2005-08-31	72.718 mi
Registration #3	2006-01-09	72.856 mi
Registration #4	2007-01-29	78.392 mi
Registration #5	2008-02-08	84.770 mi
Registration #6	2009-02-18	92.054 mi
Registration #7	2010-02-20	95.918 mi
Registration #8	2011-02-18	99.216 mi
Registration #9	2011-02-18	99.217 mi
Registration #10	2012-02-20	102.247 mi
Registration #11	2012-02-21	102.247 mi
Registration #12	2013-02-20	104.474 mi
Registration #13	2013-02-21	104.479 mi
Registration #14	2014-02-14	106.729 mi
Registration #15	2015-02-14	109.077 mi
Registration #16	2016-02-14	111.327 mi
Registration #17	2017-02-14	113.577 mi
Registration #18	2018-02-14	115.827 mi
Registration #19	2019-02-14	118.077 mi
Registration #20	2020-02-14	120.327 mi
Registration #21	2021-02-14	122.577 mi
Registration #22	2022-02-14	124.827 mi
Registration #23	2023-02-14	127.077 mi
Registration #24	2024-02-14	129.327 mi
Registration #25	2024-02-19	131.577 mi
Registration #26	2024-02-19	131.577 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1482 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1369 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	213532