



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 2

Date	2022-02-22
Pictures	29
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-21
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	33
Total items failed	6

MOT #19	2024-01-20 15:42
MOT test number	264713351316
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18	2024-01-20 15:42
MOT test number	900649467249
Result	✗ Failed
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #17	2023-01-21 11:38
MOT test number	327746102020
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16** 2023-01-21 11:38**MOT test number** 873423186655**Result** ✗ Failed

Pass with rectification Nearside Front Upper Suspension component attachment bracket/mounting likely to become detached shock mount (5.3.3 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15 2022-01-21 11:59**MOT test number** 425859626939**Result** ✓ Passed**MOT #14** 2022-01-20 11:21**MOT test number** 260042059952**Result** ✗ Failed

MAJOR Front Brake disc contaminated (1.1.14 (b))

MAJOR Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #13 2021-04-28 11:09**MOT test number** 684656781386**Result** ✓ Passed

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #12**

2021-04-28 09:48

MOT test number

830463087119

Result**✗ Failed**

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11

2020-01-07 11:18

MOT test number

418298761631

Result**✓ Passed**

Advice Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Nail in tyre

**MOT #10** 2020-01-07 11:18**MOT test number** 903509271770**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (ii))**MOT #9** 2018-09-21 08:13**MOT test number** 398444837666**Result** ✓ Passed**MOT #8** 2018-09-21 08:13**MOT test number** 516315352144**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #7** 2017-09-25 14:58**MOT test number** 958450120695**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear Upper Coil spring mounting corroded but not seriously weakened both sides (2.4.C.3c)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-09-27 11:29**MOT test number** 356232999372**Result** ✓ Passed

**MOT #5** 2015-09-15 15:42**MOT test number** 654777199238**Result** ✓ Passed**MOT #4** 2014-09-23 10:30**MOT test number** 427616764281**Result** ✓ Passed**MOT #3** 2013-09-17 10:39**MOT test number** 985270463200**Result** ✓ Passed**Notice** Nearside front tyre slight wear on outer edge**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-09-14 12:20**MOT test number** 686678052291**Result** ✓ Passed**MOT #1** 2011-09-28 16:17**MOT test number** 295881971264**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-02-13
Last registration	2024-01-20
Complete history	See info



Registration #1	2008-02-13	11 mi
Registration #2	2011-09-28	13.300 mi
Registration #3	2012-09-14	16.766 mi
Registration #4	2013-09-17	21.158 mi
Registration #5	2014-09-23	25.955 mi
Registration #6	2015-09-15	29.786 mi
Registration #7	2016-09-27	34.506 mi
Registration #8	2017-09-25	39.234 mi
Registration #9	2018-09-21	43.129 mi
Registration #10	2018-09-21	43.129 mi
Registration #11	2020-01-07	47.150 mi
Registration #12	2020-01-07	47.150 mi
Registration #13	2020-01-07	47.150 mi
Registration #14	2020-01-07	47.150 mi
Registration #15	2020-01-07	47.150 mi
Registration #16	2020-01-07	47.150 mi
Registration #17	2020-01-07	47.150 mi
Registration #18	2020-01-07	47.150 mi
Registration #19	2020-01-07	47.150 mi
Registration #20	2020-01-07	47.150 mi
Registration #21	2020-01-07	47.150 mi
Registration #22	2020-01-07	47.150 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

8E18431