





report date: 2024-03-28

### General information

Make	VOLVO
Model	XC60 D4 R-DESIGN AWD
Colour	Red
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

### Entry 3

Date 2021-10-22

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2


Date	2021-07-13
------	------------

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

### Entry 1

Date 2021-07-12

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

WG67URX report date: 2024-03-28

MOT expiry date	2024-12-04
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	1

MOT #6		2023-12-02 10:59
MOT test	number	958520444681
Result		✓ Passed
Next expiry date 2024-12-		2024-12-04
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2022-12-03 09:30
MOT test number	267900632164
Result	✓ Passed
MOT #4	2022-12-03 09:30
MOT test number	515003716914
Result	<b>▼</b> Failed
Pass with rectification (b) (ii))	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #3	2021-11-12 10:00
MOT test number	209388219653
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (iii))

MOT #1

2020-12-03 09:24

MOT test number

644426677264

Result

MAJOR Offside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check





Expires: 4 December 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK NA
Plate since	
	More info >



report date: 2024-03-28

### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-12-05
Last registration	2023-12-02
Complete history	See info



Registration #1	2017-12-05	20 mi
Registration #2	2020-12-03	25.410 mi
Registration #3	2020-12-03	25.419 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1802 kg
Max. allowed weight	2500 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles2Engine number2277452