



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA DYNAMIC
Colour	Blue
Year of manufacture	2004
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-11
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-10-17
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	22
Total items failed	11

MOT #23 2023-10-18 11:57**MOT test number** 926318720543**Result** ✓ Passed**Next expiry date** 2024-10-17**Advice** Tyre slightly damaged/cracking or perishing o/s/r tire has age related cracking various (5.2.3 (d) (ii))**Advice** Tyre worn close to legal limit/worn on edge n/s/f tire wearing close to limit on edges (5.2.3 (e))**MOT #22** 2022-09-15 09:29**MOT test number** 448588879678**Result** ✓ Passed**Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))**Advice** Coolant leak**Advice** Tyre slightly damaged/cracking or perishing All 4 tyres (5.2.3 (d) (ii))**MOT #21** 2021-10-05 07:34**MOT test number** 559767736412**Result** ✓ Passed**MOT #20** 2020-09-30 07:52**MOT test number** 628960148493**Result** ✓ Passed

**MOT #19** 2019-09-11 15:06**MOT test number** 147081618752**Result** Passed**MOT #18** 2019-09-11 09:59**MOT test number** 552089448764**Result** Failed**MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #17** 2018-10-09 15:48**MOT test number** 751404379662**Result** Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust starting to deteriorate**Advice** Light corrosion on suspension**MOT #16** 2017-10-10 14:36**MOT test number** 546969179826**Result** Passed**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #15** 2017-10-10 08:42**MOT test number** 183420775586**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Nearside Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2016-10-03 14:45**MOT test number** 930012070701**Result** ✓ Passed**MOT #13** 2016-10-01 08:56**MOT test number** 902215889576**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #12** 2015-09-25 13:47**MOT test number** 398596163284**Result** ✓ Passed

**MOT #11** 2015-09-25 09:25**MOT test number** 639957476460**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2014-09-22 17:55**MOT test number** 826145264273**Result** ✓ Passed**MOT #9** 2014-09-22 17:55**MOT test number** 725305964289**Result** ✗ Failed**Pass with rectification** Offside Rear wheel cylinder leaking (3.6.A.1)**MOT #8** 2013-09-25 13:49**MOT test number** 627308463223**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2012-09-28 16:39**MOT test number** 297282472216**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2012-09-27 12:10**MOT test number** 316241972278**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tie bar/rod ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Fail** Offside Front Shock absorber has negligible damping effect (2.7.5)**Advice** Nearside Front Tie bar/rod ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2011-09-21 11:01**MOT test number** 565294861299**Result** ✓ Passed**MOT #4** 2010-09-16 14:56**MOT test number** 873919350292**Result** ✓ Passed**MOT #3** 2009-09-28 12:25**MOT test number** 773611379233**Result** ✓ Passed**MOT #2** 2008-09-25 12:48**MOT test number** 641829168287**Result** ✓ Passed**MOT #1** 2007-09-25 15:06**MOT test number** 484138067225**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WF54MPZ
Plate since	2019-03-29
Current registration	WF54MPZ
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-09-29
Last registration	2023-10-18
Complete history	See info



Registration #1	2004-09-29	16 mi
Registration #2	2007-09-25	15.554 mi
Registration #3	2008-09-25	21.279 mi
Registration #4	2009-09-28	26.247 mi
Registration #5	2010-09-16	31.163 mi
Registration #6	2011-09-21	35.430 mi
Registration #7	2012-09-27	40.242 mi
Registration #8	2012-09-28	40.244 mi
Registration #9	2013-09-25	43.066 mi
Registration #10	2014-09-22	45.403 mi
Registration #11	2015-09-25	49.704 mi
Registration #12	2015-09-25	49.704 mi
Registration #13	2016-09-25	51.277 mi
Registration #14	2017-09-25	51.277 mi
Registration #15	2018-09-25	51.277 mi
Registration #16	2019-09-25	51.277 mi
Registration #17	2020-09-25	51.277 mi
Registration #18	2021-09-25	51.277 mi
Registration #19	2022-09-25	51.277 mi
Registration #20	2023-09-25	51.277 mi
Registration #21	2024-09-25	51.277 mi
Registration #22	2025-09-25	51.277 mi
Registration #23	2026-09-25	51.277 mi
Registration #24	2027-09-25	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1589 mm
Height	1578 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats 4

Engine number	2437743
---------------	---------