





report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H EXECUTIVE EDITION
Colour	Grey
Year of manufacture	2015
Top speed	125 mph
0 - 60 mph	8.1 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

		1
ᆮ	HLIV	-

ciitiy 1	
Date	2021-08-06
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-05-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	8
Total items failed	0

MOT #7	2023-04-27 13:10
MOT test number	761401557493
Result	✓ Passed
Next expiry date	2024-05-24
Advice Front Brake disc worn, but not excessively both front disc also got	t lipped (1.1.14 (a) (i))

MOT #6		2022-05-04 07:54
MOT test	number	431942420472
Result		✓ Passed
Minor (i))	Offside Rear Rear reflector defective or damaged by up to 50% of the reflecti	ng surface (4.8.1 (a)

MOT "F		2022 04 20 14 00
MOT #5		2022-04-29 14:00
MOT test	number	827456972613
Result		X Failed
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Minor (i))	Offside Rear Rear reflector defective or damaged by up to 50% of the r	reflecting surface (4.8.1 (a)

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number
967977247064

Result
Passed

Minor
Front Windscreen wiper blade defective Both sides (3.4 (b) (i))

Advice
Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor
Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

 MOT #3
 2019-05-20 15:39

 MOT test number
 903660709079

 Result
 ✓ Passed

MOT #2 2019-04-16 12:25

MOT test number 829984793500

Result ✓ Passed

MOT #1 2018-04-23 10:02

MOT test number 156275413501

Result \(\sqrt{Passed} \)

Advice Both rear tyres wearing inner edge slightly

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim	
Owner	nictory
COVIDE	11151017
O	,

For how long did the current and previous owner(s) have this LEXUS? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-04-24
Last registration	2023-04-27
Complete history	See info



Registration #1	2015-04-24	28 mi
Registration #2	2018-04-23	40.379 mi
Registration #3	2019-04-16	52.969 mi
Registration #4	2019-05-20	53.094 mi
Registration #5	2021-05-25	65.353 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number 2AR1249887