



UK

BJI2XZH

report date: 2024-03-29

General information

| | |
|---------------------|--------------------|
| Make | FORD |
| Model | TRANSIT 280 LR P/V |
| Colour | White |
| Year of manufacture | 2012 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 98 BHP |
| Max. torque | 310 Nm at 1.300 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.3 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 43.5 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-04 |
| Pictures | 5 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-07-04 |
| MOT pass rate | 57 % |
| MOT passed | 8 |
| Failed MOT tests | 6 |
| Total advice items | 37 |
| Total items failed | 29 |

| | |
|------------------|--|
| MOT #14 | 2022-07-05 15:42 |
| MOT test number | 700048447330 |
| Result | ✓ Passed |
| Next expiry date | 2023-07-04 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

**MOT #13**

2022-06-24 09:25

MOT test number

344724424448

Result**✗ Failed**

Fail Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Headlamp aim too high (4.1.2 (a))

Fail Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin worn to 2mm (1.1.13 (a) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit plate limit 0.53 (8.2.2.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Headlamp aim too low (4.1.2 (a))

MOT #12

2021-06-04 08:31

MOT test number

761250958104

Result**✓ Passed**

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11**

2021-06-04 08:31

MOT test number

570280524346

Result**✗ Failed****Pass with rectification**

Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification

Offside Rear Position lamp not working (4.2.1 (a) (ii))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10

2020-05-27 12:59

MOT test number

688328511400

Result**✓ Passed****Minor**

Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice

Nearside front headlight damaged

MOT #9

2019-06-26 12:57

MOT test number

159325565034

Result**✓ Passed****Advice**

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor

Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8**

2019-06-26 08:44

MOT test number

559222184864

Result**✗ Failed****Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Central Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #7**

2018-06-12 10:30

MOT test number

867744683818

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2018-06-12 08:30**MOT test number** 670808095139**Result** ✗ Failed

Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2017-06-03 08:16**MOT test number** 889057853740**Result** ✓ Passed**MOT #4** 2016-06-14 14:56**MOT test number** 312906703072**Result** ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit 195/70/r15c tread on limit inner edge. (4.1.E.1)



MOT #3

2016-06-14 14:23

MOT test number

516609890992

Result

✗ Failed

- Fail

Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail

Rear Registration plate lamp not working Both (1.1.C.1d)
- Advice

Offside Rear Tyre worn close to the legal limit 195/70/r15c tread on limit inner edge. (4.1.E.1)
- Fail

Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail

Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

MOT #2

2015-05-01 16:33

MOT test number

817251825171

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Oil leak



MOT #1

2015-05-01 16:33

MOT test number

609651725122

Result

✗ Failed

- Pass with rectification

Offside Stop lamp not working (1.2.1b)
- Notice

Oil leak
- Pass with rectification

Offside Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification

Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification

Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
17 October 2022

✕
MOT

Expired:
4 July 2023

Tax status

Expired at 17 October 2022

Days left

559 days too late

MOT expiry date

4 July 2023

Full MOT history

[See MOT history](#)



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BJ12XZH |
| Plate since | 2024-03-29 |
| Current registration | BJ12XZH |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2012-05-09 |
| Last registration | 2022-07-05 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2012-05-09 | 17 mi |
| Registration #2 | 2015-05-01 | 59.267 mi |
| Registration #3 | 2016-06-14 | 83.204 mi |
| Registration #4 | 2016-06-14 | 83.204 mi |
| Registration #5 | 2017-06-03 | 102.204 mi |
| Registration #6 | 2018-06-12 | 119.294 mi |
| Registration #7 | 2018-06-12 | 119.294 mi |
| Registration #8 | 2019-06-26 | 132.819 mi |
| Registration #9 | 2020-06-26 | 149.819 mi |
| Registration #10 | 2021-06-26 | 166.819 mi |
| Registration #11 | 2022-06-26 | 183.819 mi |
| Registration #12 | 2023-06-26 | 200.819 mi |
| Registration #13 | 2024-06-26 | 217.819 mi |
| Registration #14 | 2025-06-26 | 234.819 mi |
| Registration #15 | 2026-06-26 | 251.819 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Engine number | BM22795 |