



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 PLUS SDI
Colour	Blue
Year of manufacture	2010
Top speed	88 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	140 Nm at 2.200 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2022-02-24
Pictures	31
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-17
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-08
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	23
Total items failed	11

MOT #18	2024-01-09 16:19
MOT test number	584247113032
Result	✓ Passed
Next expiry date	2025-01-08

MOT #17	2024-01-09 12:00
MOT test number	361703936172
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2023-01-09 12:16
MOT test number	973795213167
Result	✓ Passed

**MOT #15**

2022-10-28 14:24

MOT test number

507211466417

Result

✓ Passed

Advice

Offside Rear Nail in tyre

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Exhaust has a minor leak of exhaust gases back box slightly leaking (6.1.2 (a))

MOT #14

2022-10-28 14:24

MOT test number

267260570519

Result

✗ Failed

Advice

Exhaust has a minor leak of exhaust gases back box slightly leaking (6.1.2 (a))

Pass with rectification

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Rear Nail in tyre

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13

2021-10-25 10:35

MOT test number

470835373464

Result

✓ Passed

MOT #12

2021-10-22 14:14

MOT test number

694612438342

Result

✗ Failed

Fail

Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice

Oil level on minimum

**MOT #11**

2020-10-07 09:07

MOT test number

360635418574

Result

✓ Passed

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Nail in tyre centre of tread**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #10**

2019-10-09 09:26

MOT test number

712155331132

Result

✓ Passed

Advice Offside Rear tyre cracking on outer wall**Advice** Nearside Rear tyre cracking on outer wall**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9**

2018-09-20 16:11

MOT test number

518518332244

Result

✓ Passed

MOT #8

2018-09-20 14:00

MOT test number

694030125279

Result

✗ Failed

Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #7** 2017-10-06 15:53**MOT test number** 390365257206**Result** ✓ Passed**Advice** Offside front disc has slight rust**Advice** Offside rear tyre outer wall slightly deteriorated**MOT #6** 2017-10-06 07:42**MOT test number** 678028461006**Result** ✗ Failed**Advice** Offside front disc has slight rust**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside rear tyre outer wall slightly deteriorated**MOT #5** 2016-10-04 10:29**MOT test number** 507900928077**Result** ✓ Passed**MOT #4** 2015-10-12 11:31**MOT test number** 895995676941**Result** ✓ Passed**MOT #3** 2015-04-27 12:40**MOT test number** 159107615128**Result** ✓ Passed**MOT #2** 2014-05-24 12:11**MOT test number** 275294844492**Result** ✓ Passed



MOT #1	2013-05-31 13:16
MOT test number	428381953151
Result	✓ Passed
<div>Notice</div> N/s/f tyre perished on outer sidewall	



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 January 2025

Tax status		Valid until 1 July
Days left		63
MOT expiry date		8 January 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	EU10HHF
Plate since	2024-03-29
Current registration	EU10HHF
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-06-02
Last registration	2024-01-09
Complete history	See info



Registration #1	2010-06-02	7 mi
Registration #2	2013-05-31	32.579 mi
Registration #3	2014-05-24	43.643 mi
Registration #4	2015-04-27	54.356 mi
Registration #5	2015-10-12	56.074 mi
Registration #6	2016-10-04	56.981 mi
Registration #7	2017-10-06	58.112 mi
Registration #8	2017-10-06	58.112 mi
Registration #9	2018-09-20	61.133 mi
Registration #10	2018-09-20	61.133 mi
Registration #11	2019-10-09	65.283 mi
Registration #12	2019-10-09	65.283 mi
Registration #13	2019-10-09	65.283 mi
Registration #14	2019-10-09	65.283 mi
Registration #15	2019-10-09	65.283 mi
Registration #16	2019-10-09	65.283 mi
Registration #17	2019-10-09	65.283 mi
Registration #18	2019-10-09	65.283 mi
Registration #19	2019-10-09	65.283 mi
Registration #20	2019-10-09	65.283 mi
Registration #21	2019-10-09	65.283 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1833 mm
Length	4405 mm
Wheel base	2682 mm
Kerb weight	1465 kg
Max. allowed weight	2232 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of seats	2

Number of axles

2

Engine number

BST105616
