



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CUSTOM 300 BASE P/V L1 H1
Colour	White
Year of manufacture	2018
Top speed	103 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	96 kW / 131 HP / 104 BHP
Max. torque	360 Nm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	44.1 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-27
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	8
Total items failed	12

MOT #5	2023-08-11 13:56
MOT test number	838732274093
Result	✓ Passed
Next expiry date	2024-08-10

MOT #4	2023-08-07 10:28
MOT test number	378901637530

Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Nearside Body component damaged and likely to cause injury door mirror casing broken with sharp edges left (6.2.1 (a) (i))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #3**

2022-07-15 10:54

MOT test number

437296658453

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2022-07-14 09:56

MOT test number

162683330097

Result

✗ Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1**

2021-06-21 11:08

MOT test number

450290017804

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-06-22
Last registration	2023-08-11
Complete history	See info



Registration #1	2018-06-22	24 mi
Registration #2	2021-06-21	49.121 mi
Registration #3	2022-07-14	66.351 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2 mm
Kerb weight	1815 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3

Number of axles	2
Engine number	JY11961