





report date: 2024-03-28

General information

Make	ТОУОТА
Model	RAV-4 VVTI XTR
Colour	Silver
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	150 BHP
Max. torque	194 Nm at 4.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	212 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-05

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-10
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #19	2024-03-02 11:33
MOT test number	296829017918
Result	✓ Passed
Next expiry date	2025-03-10
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #18	2024-03-02 11:33	
MOT test number	303326483226	
Result	X Failed	
Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))		
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))		

MOT #17	2023-03-04 14:07
MOT test number	571903884962
Result	✓ Passed

CarCheck.co.uk page 3/13



Result

Advice

MOT #14

GU07HWZ

report date: 2024-03-28

✓ Passed

2021-02-19 16:16

MOT #16 2022-02-19 11:45
MOT test number 143270165768

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Play in steering rack inner joint(s)

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15 2021-02-19 16:16

MOT test number 361468942128

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT test number 273294159464

273294139404

Result X Failed

Pass with rectification Offside Front Valve stem seriously damaged (5.2.3 (j))

Pass with rectification Nearside Front Valve stem seriously damaged (5.2.3 (j))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13 2020-03-05 16:25

MOT test number 777782918356

Result ✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #12	2019-03-08 14:48

MOT test number 799211147359

MOT #11 2018-02-21 10:36

MOT test number 805154996968

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10 2017-03-08 11:10

MOT test number 657519731509

Result \rightarrow Passed

MOT #9 2016-02-29 10:39

MOT test number 876373445492

MOT #8 2015-03-03 11:36

MOT test number 228432665002

Result \(\sqrt{Passed} \)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2014-02-26 17:32

MOT test number 206137254077

CarCheck.co.uk page 5/13



Pass with rectification

GU07HWZ

report date: 2024-03-28

MOT test number

Result

Pass with rectification (8.2.2)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5

MOT test number

957444943094

Result

✓ Passed

MOT #4

MOT test number

108866942086

Result

Notice Front brake discs showing slight corrosion

 MOT #3
 2011-02-17 15:35

 MOT test number
 317458341093

 Result
 ✓ Passed

MOT #2 2010-02-16 14:08

MOT test number 164527140417

Result ✓ Passed

MOT #1 2010-02-16 14:08

MOT test number 892497240016

Result X Failed

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincore

GU07HWZ

report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this TOYOTA had different number plates.

More info >



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-10
Last registration	2024-03-02
Complete history	See info



Registration #1	2007-03-10	8 mi
Registration #2	2010-02-16	11.953 mi
Registration #3	2011-02-17	16.450 mi
Registration #4	2012-02-15	19.905 mi
Registration #5	2013-02-13	23.210 mi
Registration #6	2014-02-26	26.558 mi
Registration #7	2015-03-03	29.996 mi
Registration #8	2016-02-29	34.815 mi
Registration #9	2017-03-08	39.158 mi
Registration #10	2018-02-21	42.902 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1720 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1560 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Engine number

1AZ5678590