



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Blue
Year of manufacture	2007
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-06
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-04-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #15 2021-04-12 10:58

MOT test number 696962132547

Result ✓ Passed

Next expiry date 2022-04-17

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Play in steering rack inner joint(s)

MOT #14 2020-03-26 11:16

MOT test number 698832635389

Result ✓ Passed

**MOT #13**

2020-03-20 09:56

MOT test number

123021241460

Result**✗ Failed****Fail**

Exhaust has a major leak of exhaust gases CENTER AND REAR (6.1.2 (a))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2019-04-10 13:40

MOT test number

395000673333

Result**✓ Passed****Advice**

Offside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #11

2018-03-27 11:20

MOT test number

194884759012

Result**✓ Passed****Advice**

Nearside Rear N/S/R tyre, tread depth getting near wear bars.

**MOT #10** 2017-04-05 11:46**MOT test number** 347715352643**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 1.74 IN MIDDLE (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit WORN ON INSIDE TREAD (4.1.E.1)**Advice** BOTH FRONT WIPER BLADES IN POOR CONDITION**MOT #9** 2016-04-12 09:18**MOT test number** 711604886216**Result** ✓ Passed**MOT #8** 2015-04-14 09:48**MOT test number** 316944305115**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2014-04-09 15:20**MOT test number** 716069094051**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-04-03 15:31**MOT test number** 195433894051**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-04-18 13:01**MOT test number** 898608803181**Result** ✓ Passed**MOT #4** 2012-08-02 10:51**MOT test number** 638495712207**Result** ✓ Passed**MOT #3** 2012-08-02 10:51**MOT test number** 775705712294**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2011-07-19 13:27**MOT test number** 975690101297**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-08-17 13:56
MOT test number	962509320282
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

×

Untaxed

Tax expired:
24 September 2021

×

MOT

Expired:
17 April 2022

Tax status

Expired at 24 September

Days left

947 days too late

MOT expiry date

17 April 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ET070TC
Plate since	2019-03-28
Current registration	ET070TC
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-08-10
Last registration	2021-04-12
Complete history	See info



Registration #1	2007-08-10	27 mi
Registration #2	2010-08-17	27.618 mi
Registration #3	2011-07-19	34.765 mi
Registration #4	2012-08-02	42.680 mi
Registration #5	2013-04-18	47.637 mi
Registration #6	2014-04-03	57.197 mi
Registration #7	2014-04-09	57.368 mi
Registration #8	2015-04-14	72.048 mi
Registration #9	2016-04-20	86.377 mi
Registration #10	2017-05-25	100.377 mi
Registration #11	2018-06-20	114.377 mi
Registration #12	2019-07-15	128.377 mi
Registration #13	2020-08-10	142.377 mi
Registration #14	2021-09-05	156.377 mi
Registration #15	2022-10-01	170.377 mi
Registration #16	2023-10-26	184.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7Y38438