





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SLK SLK200 BLUEEFFICIENCY AMG SPOR
Colour	Grey
Year of manufacture	2012
Top speed	147 mph
0 - 100 km/h	7.0 seconds
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	135 kW / 184 HP / 184 BHP
Max. torque	270 Nm at 1.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	151 g/km
CO2 label	G



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-10-07

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-31
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #7	2023-05-11 11:12
MOT test number	758148740305
Result	✓ Passed
Next expiry date	2024-05-31

MOT #6		2022-05-23 09:15
MOT test	number	505649793239
Result		✓ Passed
Advice	Slight cracking on rear tyres	
Advice	Slight corrosion on front brake discs	

MOT #5		2021-05-12 11:28
MOT test	number	730470136553
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4		2020-05-19 08:45
MOT test	number	901746714593
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

Nearside Front Wheel bearing has slight play (5.1.3 (a) (l))	
MOT #3	2019-05-17 11:31
MOT test number	847618374969
Result	✓ Passed
MOT #2	2018-06-01 10:32
MOT test number	517166578305
Result	✓ Passed
MOT #1	2017-03-13 09:19
MOT test number	611586780150
Result	✓ Passed
Advice Slight oil leak - gearbox area	

Result	✓ Pas	ssed
Advice	Slight oil leak - gearbox area	
Advice	Front brake discs are slightly worn/lipped and corroding	
Advice in corrosion	Rear brake discs are in very poor condition on inner faces . app. 50% of the inner face is covere n and heavily lipped.	d

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner matery	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2012-12-11
Last registration	2023-05-11
Complete history	See info



Registration #1	2012-12-11	12 mi
Registration #2	2017-03-13	42.433 mi
Registration #3	2018-06-01	46.157 mi
Registration #4	2019-05-17	53.447 mi
Registration #5	2020-05-19	58.974 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1370 kg
Max. allowed weight	1785 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of axles	2
Engine number	27186130525589

CarCheck.co.uk page 11/11