





report date: 2024-03-28

General information

Make	NISSAN
Model	JUKE TEKNA
Colour	White
Year of manufacture	2019
Top speed	110 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	144 Nm at 4.000 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

-	٠	B43.4	,	1
ш	L	ΙV		ж,

ciitiy 1	
Date	2022-06-07
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-03-06
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #5		2024-03-07 13:32
MOT test	number	279351661190
Result		✓ Passed
Next expi	ry date	2025-03-06
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice	Outer sill covers obscuring some prescribed areas	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Parking brake lever defective but can be satisfactorily operated high travel (1.1.6	5 (d))

MOT #4		2023-03-02 15:01
MOT test	number	271757849749
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #3 2023-03-02 08:48

MOT test number 110568750737

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Spare tyre defective tyre weld out of date 10/22

MAJOR Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #2 2022-02-17 14:44

MOT test number 270315124733

Result
✓ Passed

Advice Front Vehicles internal headlight adjuster altered to recheck lights

MOT #1 2022-02-17 14:44

MOT test number 631642027380

Result ★ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Vehicles internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner history		
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		.N

	More info	>
Plate changes See in this check if this NISSAN had different number plates.		
See in this check if this Missaiv had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-07
Last registration	2024-03-07
Complete history	See info



Registration #1	2019-03-07	24 mi
Registration #2	2022-02-17	12.000 mi
Registration #3	2022-02-17	12.000 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	81%
Pedestrian	41%
Safety systems	71%
Overall rating	75%
Video	see crash video

View the complete NISSAN factory list for this vehicle <u>here</u>.



More info >

Dimensions & weight

Width	1765 mm
Height	1565 mm
Length	4135 mm
Wheel base	2530 mm
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	46 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

559144R