





report date: 2024-03-29

## General information

Make	CITROEN
Model	BERLINGO 1000 ENTERPRISE M BLUEHDI S/S
Colour	Grey
Year of manufacture	2019
Top speed	103 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



LX19VWM report date: 2024-03-29

Internet history

## Entry 2

Date	2022-03-25
Pictures	1
Listing price	View report



source: autoonline.co.uk

#### Entry 1

Date	2022-03-23	
Pictures	1	
Listing price	<u>View report</u>	



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2024-10-27
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #4	2023-10-21 14:24
MOT test number	413310988829
Result	<b>✓</b> Passed
Next expiry date	2024-10-27
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	))
Advice Nearside Front Road wheel slightly distorted Outer rim (5.2.2 (c) (i))	
Minor (i))  Offside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1 (b)
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or c (d) (i))	cords Outer sidewall (5.2.3

MOT #3	2023-10-20 15:57
MOT test number	753904519490
Result	<b>X</b> Failed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a)	) (i))
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4	(b) (ii))
Advice Nearside Front Road wheel slightly distorted Outer rim (5.2.2 (c) (i))	
Minor Offside Registration plate lamp inoperative in the case of multiple lam (i))	ips or light sources (4.7.1 (b)
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.	4 (b) (ii))
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply of (d) (i))	or cords Outer sidewall (5.2.3

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-10-28 15:24

**MOT test number** 129593824324

MOT #1 2022-03-01 10:21

MOT test number 222203014314

**Result** ✓ Passed

**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	27 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11




report date: 2024-03-29

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		DEN
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	UK WEST	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-03-01
Last registration	2023-10-21
Complete history	See info



Registration #1	2019-03-01	7 mi
Registration #2	2022-03-01	27.254 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



LX19VWM report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	91%
Children	81%
Pedestrian	58%
Safety systems	68%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1848 mm
Height	1840 mm
Length	4403 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	2370 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JCAV0018347

CarCheck.co.uk page 11/11