



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA 16V EXCLUSIV
Colour	Black
Year of manufacture	2006
Top speed	127 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





MOT history

MOT expiry date	2024-06-29
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	27
Total items failed	7

MOT #20	2023-06-30 15:16
MOT test number	760266395701
Result	✓ Passed
Next expiry date	2024-06-29

MOT #19	2023-06-29 11:00
MOT test number	513191901509
Result	✗ Failed
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18	2023-03-01 13:09
MOT test number	543828466077
Result	✓ Passed
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2023-02-23 09:19

MOT test number

835980946222

Result

✗ Failed

Fail Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16**

2022-02-23 10:14

MOT test number

365639255992

Result

✓ Passed

Advice Brake pedal wearing smooth (1.1.2 (c))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing + low on inner edge (5.2.3 (d) (ii))**MOT #15**

2021-02-27 09:41

MOT test number

938922346237

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))

**MOT #14** 2020-02-12 13:52**MOT test number** 676049683566**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**MOT #13** 2020-02-06 14:41**MOT test number** 997667319221**Result** ✗ Failed**Advice** Offside Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2019-02-07 11:32**MOT test number** 806294260825**Result** ✓ Passed**MOT #11** 2018-02-09 12:29**MOT test number** 542128447137**Result** ✓ Passed**MOT #10** 2017-02-05 08:55**MOT test number** 191301198799**Result** ✓ Passed

**MOT #9** 2016-02-09 17:25**MOT test number** 817643892154**Result** ✓ Passed**Advice** Items removed from drivers view**MOT #8** 2016-02-09 13:38**MOT test number** 760735822930**Result** ✗ Failed**Advice** Items removed from drivers view**Fail** Fuel system component leaking Fuel filter (7.2.3)**MOT #7** 2015-02-16 14:43**MOT test number** 628037045070**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #6** 2014-02-17 12:36**MOT test number** 595728344078**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-02-18 14:41**MOT test number** 688079843063**Result** ✓ Passed**MOT #4** 2012-02-21 12:24**MOT test number** 239822352088**Result** ✓ Passed

**MOT #3** 2011-02-19 11:27**MOT test number** 128890751070**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-02-12 12:33**MOT test number** 339463641003**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-02-26 15:28**MOT test number** 822457150019**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-08-18
Last registration	2023-06-30
Complete history	See info



Registration #1	2006-08-18	21 mi
Registration #2	2010-02-26	19.875 mi
Registration #3	2011-02-12	25.160 mi
Registration #4	2011-02-19	25.160 mi
Registration #5	2012-02-21	29.817 mi
Registration #6	2013-02-18	34.102 mi
Registration #7	2014-02-17	38.264 mi
Registration #8	2015-02-16	41.326 mi
Registration #9	2016-02-09	48.695 mi
Registration #10	2016-02-09	48.708 mi
Registration #11	2017-02-05	53.467 mi
Registration #12	2018-02-05	58.226 mi
Registration #13	2019-02-05	62.985 mi
Registration #14	2020-02-05	67.744 mi
Registration #15	2021-02-05	72.503 mi
Registration #16	2022-02-05	77.262 mi
Registration #17	2023-02-05	82.021 mi
Registration #18	2024-02-05	86.780 mi
Registration #19	2025-02-05	91.539 mi
Registration #20	2026-02-05	96.298 mi
Registration #21	2027-02-05	101.057 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1905 mm
Height	1364 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1215 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	20GV9335