



report date: 2024-03-29

General information

Make	VOLVO
Model	S40
Colour	Blue
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-27
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-02-22
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #16	2023-02-23 12:59
MOT test number	742295308280
Result	✓ Passed
Next expiry date	2024-02-22

MOT #15	2022-02-19 11:43
MOT test number	314594329596
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2022-02-16 17:01

MOT test number

832848702066

Result

✗ Failed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm insecurely attached (5.3.3 (a) (i))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Lower Suspension arm insecurely attached (5.3.3 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Rear Lower Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #13

2021-11-11 09:25

MOT test number

902073015027

Result

✗ Failed

- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Fail** Power steering component leaking Steering rack (2.1.5 (a))

MOT #12

2020-11-19 13:27

MOT test number

581945707372

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #11	2019-05-10 10:40
----------------	------------------

MOT test number	507605918078
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2018-04-30 11:39
----------------	------------------

MOT test number	703406305019
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2018-04-27 10:02
---------------	------------------

MOT test number	210093126217
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Front wheel bearing rough when rotated (2.5.A.2)
-------------	---

MOT #8	2017-04-26 15:16
---------------	------------------

MOT test number	595272035992
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2016-04-21 10:28
---------------	------------------

MOT test number	301935924158
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Both rear tyres starting to perish.
---------------	-------------------------------------

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #6	2015-05-13 12:17
---------------	------------------

MOT test number	366573235141
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #5** 2015-05-13 12:17**MOT test number** 128643335173**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2014-05-19 14:56**MOT test number** 139199534190**Result** ✓ Passed**MOT #3** 2013-03-21 13:09**MOT test number** 978280983068**Result** ✓ Passed**MOT #2** 2012-03-23 12:04**MOT test number** 618183582053**Result** ✓ Passed**MOT #1** 2011-03-24 15:06**MOT test number** 655933881024**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2024

X

MOT

Expired:
22 February 2024

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	22 February 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-04-29
Last registration	2023-02-23
Complete history	See info



Registration #1	2008-04-29	21 mi
Registration #2	2011-03-24	18.457 mi
Registration #3	2012-03-23	23.154 mi
Registration #4	2013-03-21	26.903 mi
Registration #5	2014-05-19	33.493 mi
Registration #6	2015-05-13	39.948 mi
Registration #7	2016-04-21	45.880 mi
Registration #8	2017-04-26	58.628 mi
Registration #9	2018-04-27	71.744 mi
Registration #10	2019-05-29	85.277 mi
Registration #11	2020-05-29	95.277 mi
Registration #12	2021-05-29	105.277 mi
Registration #13	2022-05-29	115.277 mi
Registration #14	2023-05-29	125.277 mi
Registration #15	2024-05-29	135.277 mi
Registration #16	2025-05-29	145.277 mi
Registration #17	2026-05-29	155.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Number of seats

4

Engine number

143891