





### General information

Make	LAND ROVER
Model	RANGE ROVER SD4 PRESTIGE
Colour	Blue
Year of manufacture	2013
Top speed	121 mph
0 - 100 km/h	9.6 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	174 g/km
CO2 label	Н








# Internet history

Entry 3	
Date	2021-09-08
Pictures	50
Listing price	View report










source: cargurus.co.uk

Entry 2	
Date	2021-06-25
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-06-25
Pictures	69
Listing price	View report







source: autotrader.co.uk



# MOT history

MOT expiry date	2022-06-02
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #8	2021-06-03 14:54
MOT test number	188781955880
Result	✓ Passed
Next expiry date	2022-06-02
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7		2021-06-03 08:59
MOT test	number	895905446527
Result		🗙 Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	

МОТ #6	2020-07-22 08:42
MOT test number	928372052332
Result	✓ Passed
	2010 11 20 15.45

MOT #5	2019-11-29 15:45
MOT test number	671191410538
Result	✓ Passed





MOT #4	2018-11-26 12:27
MOT test number	915080737907
Result	✓ Passed
MOT #3	2017-12-01 09:51
MOT test number	862249290789
Result	✓ Passed
Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2017-12-01 09:51
MOT test number	451365090698
Result	× Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice Nearside Rear B	rake pad(s) wearing thin (3.5.1g)
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively
(8.2.2)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2016-11-30 15:06
MOT test number	283775175838
Result	Passed
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)	



**OV63AKP** report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 1 June 2021	X MOT Expired: 2 June 2022
Tax status	Expired at 1 June 2021
Days left	1064 days too late
MOT expiry date	2 June 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





#### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET I
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





**影**(

K ROLE IN

## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF CONTRACTOR OF CONTRA	
*********	
********	
And a second sec	
***********	
********	
	More info >
Plate changes	

Rumber of plates

Current registration

Plata since

Current registration	
Plate since	
	More info >





#### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-16
Last registration	2021-06-03
Complete history	See info



Registration #1	2013-10-16	19 mi
Registration #2	2016-11-30	37.055 mi
Registration #3	2017-12-01	51.392 mi
Registration #4	2017-12-01	51.392 mi
Registration #5	2018-11-26	57.430 mi
Registration #6	2019-11-29	64.882 mi
Registration #7		11.777 mi
Registration #7 Registration #8		10.000 est
		00.000 ees 00.000 ees 00.000 ees
Registration #8		00.000 est 0.000 est 00.000 est 00.000 est
Registration #8 Registration #9		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460





# Safety ratings

NCAP rating	****
Adult	86%
Children	75%
Pedestrian	41%
Safety systems	86%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	2125 mm
Height	1640 mm
Length	4355 mm
Wheel base	2660 mm
Kerb weight	1685 kg
Max. allowed weight	2350 kg
Additional information	
Additional information Fuel tank capacity	58 I
	58 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5