



Mercedes-Benz

LSIOEXE

report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Black
Year of manufacture	2010
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-22
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-15
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	32
Total items failed	19

MOT #14	2023-05-30 09:02
MOT test number	201794217362
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-06-16 07:37
MOT test number	878723720264
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2021-03-30 07:28

MOT test number

553805014034

Result

✓ Passed

- Advice** Fuel Pipe/s corroded Main feed and breather pipes
- Advice** Macpherson strut corroded but not seriously weakened Both front struts corroded (5.3.3 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both rear bushes worn (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #11

2021-03-25 11:45

MOT test number

831704834727

Result

✗ Failed

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both rear bushes worn (5.3.4 (a) (i))
- Advice** Macpherson strut corroded but not seriously weakened Both front struts corroded (5.3.3 (b) (i))
- Advice** Fuel Pipe/s corroded Main feed and breather pipes
- Advice** Coil spring corroded Both front coil springs corroded (5.3.1 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Brake hose connection leaking on a hydraulic braking system OSF Flexi leaking at caliper (1.1.12 (c) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10**

2020-03-16 15:44

MOT test number

545044504506

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9

2019-03-13 16:59

MOT test number

306735894962

Result

✓ Passed

- Advice** Offside Front Inner Play in steering rack inner joint(s)
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

**MOT #8** 2019-03-12 13:39**MOT test number** 663735783239**Result** ✗ Failed**Advice** Central Front Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Advice** Offside Front Inner Play in steering rack inner joint(s)**Fail** Offside Rear Valve stem seriously damaged (5.2.3 (j))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Seat belt not functioning as intended seat belt receiver (7.1.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #7** 2018-03-27 11:15**MOT test number** 852819785294**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)

**MOT #6** 2017-03-28 15:23**MOT test number** 130102326811**Result** ✓ Passed**MOT #5** 2017-03-28 15:23**MOT test number** 970365078027**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2015-06-27 11:07**MOT test number** 929108175103**Result** ✓ Passed**MOT #3** 2014-06-30 17:20**MOT test number** 376631284141**Result** ✓ Passed**MOT #2** 2014-06-30 17:20**MOT test number** 388631884164**Result** ✗ Failed**Pass with rectification** Front Bonnet cannot be secured in the closed position (8.4.1)**Pass with rectification** Front Horn control missing (1.6.1)**MOT #1** 2013-07-03 16:11**MOT test number** 569974983110**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
15 June 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	LS10EXE
Plate since	2019-06-29
Current registration	LS10EXE
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-29
Last registration	2023-05-30
Complete history	See info



Registration #1	2010-03-29	20 mi
Registration #2	2013-07-03	40.114 mi
Registration #3	2014-06-30	46.855 mi
Registration #4	2015-06-27	57.822 mi
Registration #5	2017-03-28	68.222 mi
Registration #6	2017-03-28	68.222 mi
Registration #7	2018-03-27	83.677 mi
Registration #8	2019-03-12	26.022 mi
Registration #9	2019-05-29	26.277 mi
Registration #10	2019-05-29	26.277 mi
Registration #11	2019-05-29	26.277 mi
Registration #12	2019-05-29	26.277 mi
Registration #13	2019-05-29	26.277 mi
Registration #14	2019-05-29	26.277 mi
Registration #15	2019-05-29	26.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030638778