





General information

| Make | VOLVO |
|---------------------|-----------------|
| Model | V90 D3 R-DESIGN |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 124 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 148 BHP |
|----------------------|---------------------|
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 2.8 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |



| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-05-08 |
| Pictures | 0 |
| Listing price | View report |

source: yesauto.com



MOT history

| MOT expiry date | 2024-12-11 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #3 | 2023-11-30 14:44 |
|------------------|------------------|
| MOT test number | 441017431676 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-11 |

| MOT #2 | 2022-12-12 11:21 |
|---|------------------|
| MOT test number | 591372584172 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #1 | 2021-10-27 11:32 |
|--------------------------|------------------|
| MOT test number | 912420350170 |
| Result | ✓ Passed |
| Advice Undertrays fitted | |



Tax & MOT check

| √ Taxed | ✓ MOT |
|------------------------|------------------------------|
| Tax due: 1 May 2024 | Expires: 11 December 2024 |
| Tax status | Valid until 1 May |
| Days left | 1 |
| MOT expiry date | 11 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second se | |
|---|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| | |
| Current registration | |
| Current registration Pate since | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles | |
|----------------------------|------------|--|
| Mileage registrations | 5 | |
| First mileage registration | 2018-10-29 | |
| Last registration | 2023-11-30 | |
| Complete history | See info | |



| Registration #1 | 2018-10-29 | 21 mi |
|-----------------|------------|------------|
| Registration #2 | | 11.777 est |
| Registration #3 | 2021-10-27 | 23.915 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 10.300 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 97% |
| Children | 87% |
| Pedestrian | 71% |
| Safety systems | 76% |
| Overall rating | 86% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1910 mm |
| Height | 1658 mm |
| Length | 4425 mm |
| Kerb weight | 1572 kg |
| Max. allowed weight | 2120 kg |
| Additional information | |
| Fuel tank capacity | 54 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 10/10 |

Engine number

2787190