





General information

Make	ΤΟΥΟΤΑ
Model	ESTIMA
Colour	White
Year of manufacture	2009
Gearbox	-

Engine & fuel consumption

Engine capacity	2.360 cc	0 < 101 A	LABEL UNKNOWN
Fuel type	Hybrid / Electric	101 - 120 ^B 121 - 140 ^P	

225+



Internet history

Entry 2

Date Pictures 2022-03-09

12

Listing price

View report



source: cargurus.co.uk

Entry	1
	_

Date

Pictures

Listing price

2021-08-17 12

View report



source: cargurus.co.uk









MOT history

MOT expiry date	2025-03-18
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	28
Total items failed	7

MOT #7		2024-03-19 12:51
MOT test	number	949362121634
Result		✓ Passed
Next expi	ry date	2025-03-18
Advice	Nearside Rear Sub-frame pin or bush worn but not resulting in excessive	movement (5.3.4 (a) (i))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Sub-frame pin or bush worn but not resulting in excessive m	novement (5.3.4 (a) (i))
Advice	Nearside Front Brake $pad(s)$ wearing thin (1.1.13 (a) (ii))	

МОТ #6		2024-03-19 12:51	
MOT test number		958917263626	
Result		🗙 Failed	
Advice Nearside Re	ear Sub-frame pin or bush worn but not resulting in e	xcessive movement (5.3.4 (a) (i))	
Advice Offside From	nt Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectificati	on Offside Rear Registration plate lamp inoperativ	ve in the case of a single lamp or	
all lamps (4.7.1 (b) (ii))			
Advice Offside Rea	r Sub-frame pin or bush worn but not resulting in exc	cessive movement (5.3.4 (a) (i))	
Advice Nearside Fr	ont Brake pad(s) wearing thin (1.1.13 (a) (ii))		





MOT #5		2023-03-07 12:30
MOT test	number	664716081140
Result		Passed
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1 (b)
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2022-01-10 16:17
MOT test	number 911563196094
Result	✓ Passed
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

MOT #3	2021-01-26 16:39
MOT test number	845541884562
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps of (b) (i))	r light sources (4.7.1
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5	.3.4 (b) (i))
Advice Offside Rear Lower Brake pad(s) wearing thin (1.1.13 (a) (ii))	






MOT #2 202	1-01-26 08:57
MOT test number 7	17895747339
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Rear fog lamp missing (4.5.1 (a) (ii))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass with rectification Offside Headlamp aim too high and too far to the right. (4.1.2 (a))	
Advice Offside Rear Lower Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Rear fog lamp switch missing (4.5.3 (a) (ii))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sou (b) (i))	rces (4.7.1

MOT #1	2020-12-21 09:56
MOT test number	907454049882
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailRear fog lamp missing (4.5.1 (a) (ii))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or (b) (i))	r light sources (4.7.1
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	



Tax & MOT check







Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2019-06-01
Last registration	2024-03-19
Complete history	<u>See info</u>



Registration #1	2019-06-01	18 mi
Registration #2	2020-12-21	79.942 mi
Registration #3	2021-01-26	80.331 mi
Registration #4	2021-01-26	80.331 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10.317 est

More info >





Car features

50225	Air conditioning
50295	
50482	
60501	
0566	
60567	
60569	

Additional information

Number of seats	7
Engine number	2AZ-2JM-2FM