



General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





## Internet history

### Entry 4

Date	2023-01-31
Pictures	40
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 3

Date	2022-12-22
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2

Date	2021-06-21
Pictures	32
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-06-17
------	------------

Pictures

7

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	49
Total items failed	5

MOT #15	2023-11-16 09:34
MOT test number	718125607043
Result	✓ Passed
Next expiry date	2024-11-17

MOT #14	2022-11-18 14:52
MOT test number	706181716478
Result	✓ Passed

**MOT #13**

2022-09-20 11:06

**MOT test number**

910696435984

**Result**

✓ Passed

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
- Advice** Exhaust system heavily corroded
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2022-09-20 11:06

**MOT test number**

350805051939

**Result****✗ Failed**

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

**Advice** Vehicles internal headlight adjuster altered to recheck lights

**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

**Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

**Advice** Offside Rear Nail in tyre

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Exhaust system heavily corroded

**Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #11**

2021-09-22 08:50

**MOT test number**

287110579693

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished slightly between treads.  
(5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2021-09-22 08:50

**MOT test number**

324512241413

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished slightly between treads.  
(5.2.3 (d) (ii))**MOT #9**

2020-09-19 10:31

**MOT test number**

125923368153

**Result**

✓ Passed

**Advice** Rear exhaust bracket broken but system still supported**MOT #8**

2019-09-28 08:26

**MOT test number**

508485305550

**Result**

✓ Passed

**MOT #7** 2018-09-22 10:54**MOT test number** 540374647383**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-09-30 08:59**MOT test number** 372770074993**Result** ✓ Passed**MOT #5** 2016-09-24 07:42**MOT test number** 225845937975**Result** ✓ Passed**MOT #4** 2015-09-12 09:46**MOT test number** 169990933032**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-09-13 10:37**MOT test number** 628556054247**Result** ✓ Passed**MOT #2** 2014-09-13 10:37**MOT test number** 417436654264**Result** ✗ Failed**Pass with rectification** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Pass with rectification** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)





MOT #1	2013-09-24 17:19
MOT test number	637187263205
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
17 November 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	17 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>PK60CBY</b>
Plate since	2024-03-28
Current registration	<b>PK60CBY</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-30
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	22 mi
Registration #2	2013-09-24	17.994 mi
Registration #3	2014-09-13	24.420 mi
Registration #4	2015-09-12	32.488 mi
Registration #5	2016-09-24	39.390 mi
Registration #6	2017-09-30	47.891 mi
Registration #7	2018-09-22	53.988 mi
Registration #8	2019-09-28	58.705 mi
Registration #9	2020-09-19	63.014 mi
Registration #10	2021-09-20	65.000 mi
Registration #11	2022-09-20	65.000 mi
Registration #12	2023-09-20	65.000 mi
Registration #13	2024-09-20	65.000 mi
Registration #14	2025-09-20	65.000 mi
Registration #15	2026-09-20	65.000 mi
Registration #16	2027-09-20	65.000 mi
Registration #17	2028-09-20	65.000 mi
Registration #18	2029-09-20	65.000 mi
Registration #19	2030-09-20	65.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1500 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1587 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	AU19126