



report date: 2024-03-29

General information

Make	MINI
Model	COOPER D AUTO COOPER D
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2


Date	2023-05-06
Pictures	4
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-06
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	7
Total items failed	3

MOT #9	2023-06-02 15:29
MOT test number	176639208152
Result	✓ Passed
Next expiry date	2024-06-01
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #8	2021-08-07 08:11
MOT test number	759676181228
Result	✓ Passed

MOT #7	2020-12-24 12:03
MOT test number	600104691421
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-12-24 10:25**MOT test number** 866610732041**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**MOT #5** 2019-08-06 07:21**MOT test number** 891328863301**Result** ✓ Passed**MOT #4** 2018-08-08 11:13**MOT test number** 192874026391**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2017-08-10 09:26**MOT test number** 535164173786**Result** ✓ Passed**MOT #2** 2016-08-12 11:07**MOT test number** 310061707728**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2016-08-12 11:07
MOT test number	419231354396
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-18
Last registration	2023-06-02
Complete history	See info



Registration #1	2013-09-18	9 mi
Registration #2	2016-08-12	15.385 mi
Registration #3	2016-08-12	15.385 mi
Registration #4	2017-08-10	16.858 mi
Registration #5	2018-08-08	23.161 mi
Registration #6	2019-08-06	35.002 mi
Registration #7	2023-06-02	35.002 mi
Registration #8	2023-06-02	35.002 mi
Registration #9	2023-06-02	35.002 mi
Registration #10	2023-06-02	35.002 mi
Registration #11	2023-06-02	35.002 mi
Registration #12	2023-06-02	35.002 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1120 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	71318453