



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SE TSI
Colour	Silver
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2025-03-03
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	31
Total items failed	3

MOT #15	2024-03-04 10:03
MOT test number	295199698466
Result	✓ Passed
Next expiry date	2025-03-03
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2023-02-24 15:37
MOT test number	616147913136
Result	✓ Passed
Advice	Rear Suspension component corroded but not seriously weakened all components slightly corroded (5.3.3 (b) (i))

MOT #13	2023-02-24 11:42
MOT test number	464099579393
Result	✗ Failed
Fail	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Rear Suspension component corroded but not seriously weakened all components slightly corroded (5.3.3 (b) (i))

**MOT #12** 2022-03-04 14:11**MOT test number** 364571829267**Result** ✓ Passed**MOT #11** 2021-10-20 14:49**MOT test number** 784139594659**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-03-23 12:53**MOT test number** 720433003125**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-03-28 15:20**MOT test number** 679137742060**Result** ✓ Passed**MOT #8** 2018-04-19 12:00**MOT test number** 810976161397**Result** ✓ Passed**Advice** Rear suspension components corroded**Advice** Exhaust corroded

**MOT #7** 2017-05-27 13:33**MOT test number** 933990066896**Result** ✓ Passed**Advice** Exhaust slightly corroded**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2017-05-27 09:52**MOT test number** 874053448810**Result** ✗ Failed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Exhaust slightly corroded**Advice** Brake disc worn, pitted or scored, but not seriously weakened requires attention (3.5.1i)**MOT #5** 2016-05-17 13:15**MOT test number** 783863574861**Result** ✓ Passed

**MOT #4** 2016-02-25 09:44**MOT test number** 292974206128**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Under trays fitted
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front front brake fluctuating, but not excessively both (3.7.B.3)
- Advice** Both rear tyres cracking on sidewalls / between tread

MOT #3 2015-03-05 15:39**MOT test number** 409414365006**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Wiper rubbers splitting
- Notice** Under-trays fitted obscuring some underside components
- Notice** Rear tyres cracking & tread distorted

MOT #2 2014-03-06 16:39**MOT test number** 335125264054**Result** ✓ Passed



MOT #1	2013-02-13 16:21
MOT test number	715734343063
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-04
Last registration	2024-03-04
Complete history	See info



Registration #1	2010-03-04	26 mi
Registration #2	2013-02-13	19.832 mi
Registration #3	2014-03-06	26.429 mi
Registration #4	2015-03-05	31.907 mi
Registration #5	2016-02-25	39.003 mi
Registration #6	2016-05-17	39.934 mi
Registration #7	2017-05-27	42.368 mi
Registration #8	2017-05-27	42.369 mi
Registration #9	2019-05-27	55.377 mi
Registration #10	2019-05-27	55.377 mi
Registration #11	2019-05-27	55.377 mi
Registration #12	2019-05-27	55.377 mi
Registration #13	2019-05-27	55.377 mi
Registration #14	2019-05-27	55.377 mi
Registration #15	2019-05-27	55.377 mi
Registration #16	2019-05-27	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2009 mm
Height	1444 mm
Length	4423 mm
Wheel base	2578 mm
Kerb weight	1487 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAV 199717