



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-11-07
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-19
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	13
Total items failed	13

MOT #23	2023-11-20 08:41
MOT test number	561801198146
Result	✓ Passed
Next expiry date	2024-11-19

MOT #22	2022-11-02 09:27
MOT test number	785252803303
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-11-01 11:11
MOT test number	408834979688
Result	✗ Failed
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #20** 2021-07-14 13:52**MOT test number** 461351852027**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge Both Front (5.2.3 (e))**Advice** Tyre slightly damaged/cracking or perishing Both Front (5.2.3 (d) (ii))**MOT #19** 2021-07-14 10:50**MOT test number** 405383389148**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge Both Front (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Tyre slightly damaged/cracking or perishing Both Front (5.2.3 (d) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #18** 2020-07-21 13:30**MOT test number** 423440318595**Result** ✓ Passed**MOT #17** 2019-04-30 10:26**MOT test number** 542908276843**Result** ✓ Passed**MOT #16** 2019-04-30 09:06**MOT test number** 879714392129**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #15** 2018-05-02 08:54**MOT test number** 828585666509**Result** ✓ Passed**MOT #14** 2018-04-28 09:55**MOT test number** 424500331707**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #13** 2017-04-24 09:13**MOT test number** 497856332843**Result** ✓ Passed**MOT #12** 2016-04-23 09:07**MOT test number** 619007467257**Result** ✓ Passed**Advice** Both centre brake pipes have surface corrosion**MOT #11** 2016-04-23 08:32**MOT test number** 291466807739**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Both centre brake pipes have surface corrosion**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #10** 2015-04-24 17:10**MOT test number** 446894015108**Result** ✓ Passed

**MOT #9** 2015-04-24 16:23**MOT test number** 419764115103**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #8** 2014-04-22 11:42**MOT test number** 775462514102**Result** ✓ Passed**MOT #7** 2013-04-23 14:56**MOT test number** 259503913458**Result** ✓ Passed**MOT #6** 2012-04-24 09:26**MOT test number** 705215612126**Result** ✓ Passed**MOT #5** 2011-03-17 10:59**MOT test number** 187146671405**Result** ✓ Passed**MOT #4** 2011-03-07 14:21**MOT test number** 906546861007**Result** ✗ Failed**Fail** Offside Rear coil spring cracked (2.4.C.1a)

**MOT #3** 2011-03-07 12:00**MOT test number** 369126861099**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear coil spring fractured (2.4.C.1a)**MOT #2** 2010-03-02 17:01**MOT test number** 532361760087**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-03-01 13:49**MOT test number** 632030960016**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
19 November 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	19 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FE07RHV
Plate since	2019-06-29
Current registration	FE07RHV
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-03-02
Last registration	2023-11-20
Complete history	See info



Registration #1	2007-03-02	12 mi
Registration #2	2010-03-01	53.309 mi
Registration #3	2010-03-02	53.309 mi
Registration #4	2011-03-07	56.539 mi
Registration #5	2011-03-07	56.552 mi
Registration #6	2011-03-17	56.649 mi
Registration #7	2012-04-24	60.661 mi
Registration #8	2013-04-23	63.881 mi
Registration #9	2014-04-22	66.658 mi
Registration #10	2015-04-24	69.094 mi
Registration #11	2015-04-24	69.094 mi
Registration #12	2016-04-23	71.385 mi
Registration #13	2016-04-23	71.389 mi
Registration #14	2016-04-23	71.389 mi
Registration #15	2016-04-23	71.389 mi
Registration #16	2016-04-23	71.389 mi
Registration #17	2016-04-23	71.389 mi
Registration #18	2016-04-23	71.389 mi
Registration #19	2016-04-23	71.389 mi
Registration #20	2016-04-23	71.389 mi
Registration #21	2016-04-23	71.389 mi
Registration #22	2016-04-23	71.389 mi
Registration #23	2016-04-23	71.389 mi
Registration #24	2016-04-23	71.389 mi
Registration #25	2016-04-23	71.389 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118