



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	Blue
Year of manufacture	2013
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 2

Date	2022-07-05
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-03
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	24
Total items failed	11

MOT #11	2023-07-29 08:39
MOT test number	905653944328
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Front and rear suspension corroded

MOT #10	2022-08-10 15:04
MOT test number	252062535305
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre slightly damaged wall (5.2.3 (d) (ii))

**MOT #9** 2022-08-01 16:04**MOT test number** 936466701185**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Outer Tyre slightly damaged wall (5.2.3 (d) (ii))**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**MOT #8** 2021-08-10 11:58**MOT test number** 975840176160**Result** ✓ Passed**MOT #7** 2021-07-29 15:42**MOT test number** 352012090635**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2020-09-17 10:20**MOT test number** 818496480703**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Items removed from driver's view prior to test Windscreen

**MOT #5** 2020-09-04 09:59**MOT test number** 414752258552**Result** ✗ Failed

- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Offside Front Items removed from driver's view prior to test Windscreen
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Brake pipe excessively corroded Front to rear (1.1.11 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Brake pipe excessively corroded Front to rear (1.1.11 (c))

MOT #4 2019-09-06 15:17**MOT test number** 642367131029**Result** ✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Tyre has sidewall damage (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at rear (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Tyre has sidewall damage (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Items removed from driver's view prior to test Windscreen

**MOT #3** 2018-08-29 10:12**MOT test number** 685487045137**Result** ✓ Passed**Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MOT #2** 2017-09-05 08:17**MOT test number** 423973685287**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #1** 2016-09-20 15:22**MOT test number** 942510606324**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine covers & under trays fitted**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** All four tyres side wall damage



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-24
Last registration	2023-07-29
Complete history	See info



Registration #1	2013-09-24	11 mi
Registration #2	2016-09-20	19.250 mi
Registration #3	2017-09-05	26.664 mi
Registration #4	2018-08-29	34.134 mi
Registration #5	2019-09-06	39.790 mi
Registration #6	2020-09-04	45.430 mi
Registration #7	2020-09-17	45.439 mi
Registration #8	2020-09-20	45.439 mi
Registration #9	2020-09-20	45.439 mi
Registration #10	2020-09-20	45.439 mi
Registration #11	2020-09-20	45.439 mi
Registration #12	2020-09-20	45.439 mi
Registration #13	2020-09-20	45.439 mi
Registration #14	2020-09-20	45.439 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Number of axles	2
Engine number	G4FDCU830563